

REF:

ASSIGNMENT

Front: _____ Date: _____

Estim: _____ Post: _____

OD / TP RES / OD RES / EVA / INV / MVTo in Vehicle No: _____at W/O 100 m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

N/S	O/S

Remark: Marsh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNL8109P Yr Regn: 2022 JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Subaru Forester C.O. 1995Colour: Red A/C: Insured / Std / NI / NASp. Reading: 33825 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: J FISK7KLSM6060084Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/60R17R: 225/60R17BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 17/09/24Survey held at NSI

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rees o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 1st CapCOE Expiry

Estimate given during: Yes (✓)
1st Survey: No ()

MV: 138KPV: 84-7KNett: 53.3K019B

Date/Time, File Pass to?

☐: Preli. Report☐: Final Report1) _____
Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

3 + R.S. \$1

Photos

Others

Add Fee: ☐: Site Insp (\$)☐: Interview (\$)☐: Tech. Inve (\$)

Report Format: _____

Report Form: _____

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GHAZALI BIN ABDULLAH @RAJAMOHAN S/O
RAJAGOPAL
BLK 236 CHOA CHU KANG CENTRAL #04-43
SINGAPORE 680236

Contact : 92261661

TAX INVOICE

Repair Code : CLM18380

Date in : 16/09/2024

Vehicle Num. : SNL8109P

Model : SUBARU FORESTER 2.0I-L EYESIGHT AWD CVT

Chassis/Eng# : JF1SK7KL5MG060084/FB20YN64281

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>torn</i>	1	917.40	✓ 917.40
REAR BUMPER LOWER DIFFUSER <i>cut</i>	1	333.40	✓ 333.40
REAR BUMPER REVERSE SENSOR <i>new</i>	2	294.20	+ 588.40
REAR BUMPER REVERSE SENSOR 'O' RING <i>new</i>	4	25.00	+ 100.00
REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	4	65.60	+ 262.40
REAR BUMPER RH REFLECTOR <i>new</i>	1	249.20	+ 249.20
REAR BUMPER RH SIDE RETAINER <i>new</i>	1	25.50	+ 25.50
REAR BUMPER TOW HOOK COVER <i>new</i>	1	21.60	+ 21.60
REAR RH KNUCKLE ARM <i>new</i>	1	342.60	+ 342.60
REAR RH KNUCKLE ARM BEARING <i>new</i>	1	266.60	+ 266.60
REAR RH SPORT RIM <i>cut</i>	1	898.60	<i>450/20</i> 898.60
Subtotal before discount			4,005.70
Percentage discount 10%			400.57
Sub-total 1			3,605.13
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	<i>30</i> 50.00
REAR RH TYRE <i>new</i>	1	380.00	<i>+</i> 380.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HAZALI BIN ABDULLAH @RAJAMOHAN S/O
RAJAGOPAL
BLK 236 CHOA CHU KANG CENTRAL #04-43
SINGAPORE 680236

Contact : 92261661

TAX INVOICE

Repair Code : CLM18380

Date in : 16/09/2024

Vehicle Num. : SNL8109P

Model : SUBARU FORESTER 2.0I-L EYESIGHT AWD CVT

Chassis/Eng# : JF1SK7KL5MG060084/FB20YN64281

Subtotal before discount	430.00
Percentage discount 0%	0.00
Sub-total 2	430.00
Parts-total	4,035.13

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	✓ 80.00
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	+ 120.00
To road test driving, check and resetting wheel alignments system.	80 100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	200 500.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	200 500.00
To apply anti-rust chemical on repaired and replaced panel.	+ 60.00
Labour Total	1,360.00
Parts & Labour Total	5,395.13

*** This is a computer-generated document which requires no signature.***

page 2
LKK Auto Consultants hereby notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
1/5 17/09/24
032ys