

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/III24060167/AUQH3E2
Date: 29/10/2024REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	
Claimant Vehicle No :	SLG3515H	Insured Vehicle No :	SNJ2784P
Date of Loss:	15/06/2024	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG3515H	Engine No:	PE20788701
Make & Model:	MAZDA 6, 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A)	Chassis No:	JM6GJ1072G0239893
Reg. Date:	28/09/2016 (Man. Year: 2016)	Odometer:	127467 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,977.36	4,369.52	1,607.84	26.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	880.00	920.00	51.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,777.36	5,249.52	2,527.84	32.50
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	7,777.36	4,200.00	3,577.36	46.00
+ GST 9.00/9.00% (S\$)	699.96	378.00	321.96	46.00
Nett Amount (S\$)	8,477.32	4,578.00	3,899.32	46.00

INSPECTION

Date of Assignment:	20/06/2024	ONE GARAGE PTE LTD (HQ)
Date Inspected:	24/06/2024 Inspected At:	8 KAKI BUKIT AVE 4 #03-33 PREMIER @ K. BUKIT
Estimated Period of Repair:	4.0 days	Singapore 415875

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Oct 2024)
Parts:	143	MAZDA 6 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG3515H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,211.90 FL	*1,211.90 FL
2	1		*FRONT BUMPER SIDE HOLDER	Cracked	58.90 FL	*58.90 FL
3	1		*FRONT BUMPER FOG LAMP	Not Necessary	325.50 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP COVER	Deformed	65.10 FL	*65.10 FL
5	1		*FRONT BUMPER FOG LAMP COVER CHROME MOULDING	Not Necessary	70.20 FL	*- FL
6	1		*HEADLAMP	Cracked	3,259.60 FL	*3,259.60 FL
7	1		*FRONT FENDER	Dented	485.10 FL	*485.10 FL
8	1		*FRONT FENDER BRACKET	Not Necessary	51.60 FL	*- FL
9	1		*FRONT FENDER INNER SHIELD	Torn	195.30 FL	*195.30 FL
10	1		*WIPER WASHER TANK	Deformed	148.50 FL	*148.50 FL
11	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
12	1		*FRONT WHEEL RIM	Not Necessary	1,000.00 FS	*- FS
13	1		*FRONT TYRE	Not Necessary	250.00 FS	*- FS
					Sub Total (S\$)	7,151.70 5,454.40
					- List Item Discount on L Items 20.00/20.00% (S\$)	1,174.34 1,084.88
					Total Parts (S\$)	5,977.36 4,369.52

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVE AND REFIT PARTS	New	800.00	400.00
2	SPRAY PAINTING TO AFFECTED AREA	New	600.00	400.00
3	WIRING CHECK	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	100.00	0.00
5	TO REMOVE FRONT BUMPER SENSOR	New	100.00	50.00
6	TO PERFORM WHEEL ALIGNMENT	New	150.00	0.00
Gross Labour Cost (\$)			1,800.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >