



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNG 1091C

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT HEADLAMP -LH	CUT	\$3,034.90	\$2,110.00
1	FRONT HEADLAMP LOWER BRACKET	CRACKED	\$127.60	\$127.60
1	FRONT BUMPER	DEFORMED	\$525.00	\$525.00
1	FRONT BUMPER SIDE LAMP	CRACKED	\$400.30	\$320.00
1	FRONT BUMPER SIDE LAMP GRILLE	CRACKED	\$150.20	\$150.20
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	\$696.00	\$0.00
1	FRONT BUMPER SIDE RETAINER	CRACKED	\$60.20	\$60.20
1	FRONT FENDER -LH	DENTED	\$1,521.60	\$490.00
1	FRONT FENDER INNER SHIELD	TORN	\$220.80	\$220.80
1	FRONT WHEEL RIM	NOT NECESSARY	\$1,550.00	\$0.00
1	FRONT WHEEL HUB	NOT NECESSARY	\$189.50	\$0.00
1	FRONT WHEEL BEARING	DAMAGED	\$155.80	\$155.80
1	FRONT SHOCK ABSORBER	NOT NECESSARY	\$424.50	\$0.00
1	FRONT KNUCKLE ARM	NOT NECESSARY	\$455.80	\$0.00
1	FRONT LOWER ARM	NOT NECESSARY	\$435.00	\$0.00
	<b>LESS 10.00 / 20.00% DISCOUNT</b>		(\$994.72)	(\$831.92)
			<b>\$8,952.48</b>	<b>\$3,327.68</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	\$80.00	\$30.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	\$60.00	\$30.00
1	FRONT TYRE (SN)	NOT NECESSARY	\$400.00	\$0.00
1	FRONT SPORT RIM COVER (SN)	CUT	\$500.00	\$200.00
			<b>\$1,040.00</b>	<b>\$260.00</b>

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING, LIGHTING AND RESETTING HEADLAMPS FOCUSING		\$80.00	\$30.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE		\$300.00	\$60.00
	TO CONDUCT WHEEL ALIGNMENT		\$180.00	\$80.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	NOT NECESSARY	\$180.00	\$0.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD ; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT		\$1,600.00	\$500.00
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT		\$1,500.00	\$400.00
			\$3,840.00	\$1,070.00
GRAND TOTAL			\$13,832.48	\$4,657.68
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$3,600.00
Report Ref No: CS/FCI24090308/Anp3m4				

**LWP**

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.