CS/FCI2409	0308/Anp3 (SNG 1091C)
The state of the s	SIGNMENT
Fiort Date:	Veh No: SNG1091C Yr Regn: 2022, July
estin * Charles	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
DO / WITP RES / OD RES / EVA / INV / MV	Truck / Trailer or .
in in thicle No:	Make: Gundan Janig and 1580
WORKS	Colour Grey, A/C: Insured / Std / NI / NA
	Sp.Reading 154801 T/Radio; Insured / Std / NI / NA
nsur@d:	Eng/No:
olicy of the	C/NO: KMHC851CV NU 293429
laines in	Gen. Cond: Good Fair / Poor / Burnt
ium Ensuit Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Cli⊖nt'sAsord)	Brake: Inorder / Jammed / Leaked / Burnt or
Vake of Vai:	Modi: Nil (S/Rim) / STD A/Rim or
**************************************	Tyre Size: F: 185/65 R15
(Poffcy Codition)	R: (85/65R15.
lemark: Theyeh had commenced its N/S 0/S	De l'action l'attication outle de l'action
ipair at the time of inspection.	TOYO / YOKO OF A Plus.
al. or Mahai Value:	Front Rear
DAC Acoldent Rport: Consistent? : Yes or No	R/Bal. Mm R/Bal. mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 96 mm L/Bal. 90 mm
Est. Repairsoays Res.; Yes or No	D.O.A. 17/09/24
Lum Sum: % 3 Val.: Yes or No	Survey held at $H^{-}(ec)$
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OL Date: Person Contacted;	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time   Action / Instruction	The ord I chassis halfle I body structure allected one to collision.
18 Istup.	COE Expiry:
	d d
	Estimate given during . Yes Co
mv: 1181C	1st Survey " No C)
PV:68.7K	V .
Nett: 49.3K	
Adrian confirmed lump sum \$3600	
(red, \$10232.48, 73%)	2446.
DateTine, File Pass to? : Prefit Report	Days Of Repair: 5
1) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/fine, File Return to?	Transportation:
2) Add	Fee; Site Insp (\$ )_8+R8_8
	: Interview (\$ ) Photos

## A-Tec Automotive Pte Ltd 8 Kaki Bukit Ave 4 #04-20 Premier Singapore 415875

18 Sep 2024

## SNG 1091 C HYUNDAI IONIQ

SNG	1091	CHICNDALIONIQ		
				Estimated Parts Price
No	Qty	Parts Description		
1	1	Front headlamp -LH Lt	\$	3,034.90
2	1	Front headlamp lower bracket and	og elseland gentledne vangen i \$	127.60
3	1	Front humper	reserved period vised beginning si\$	525.00
4	1	Front humner side lamp	Secretarios selectores \$	400.30
5	1	Front bumper side lamp grille	S	
6	1	Front bumper reinforcement	\$	
7	1	Front bumper side retainer Lucia	\$	
8	1	Front fender -LH	\$	/
9	1	Front fender inner shield	\$	220.80
10	1	Front wheel rim	\$	1,550.00
11	1	Front wheel hub Ru	\$	189.50
12	1	Front wheel bearing 2	\$	155.80
13	1	Front shock absorber	\$	424.50
14	1	Front knuckle arm	\$	455.80
15	1	Front lower arm	\$	435.00
			\$	9,947.20
			less 10%	994.72
			\$	8,952.48

No	Qty	Parts Description	Estimated Parts Price
		Special Nett Items	
1	1	Front bumper clip (1 set)	\$ 80.00
2	1	Front fender inner shield clip (1 set)	\$ _60.00
3	1	Front tyre 100	\$ 400.00
4	1	Front sport rim Cover Co	\$ _500.00 200
	•	Trem operium 60 v W	\$ 1,040.00

Total parts:

9,992.48

No	<b>Description</b>		Labour Charges
1	To check wiring, lighting and resetting headlamps focusing.	\$	80.00 30
2	To remove and refit front undercarriage.	\$	300.00 60
3	To conduct wheel alignment.	\$	180.00 80
4	To apply undercoating on repaired and replaced panel.	\$	180.00 +
5	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damaged consistent to the accident.	\$	1,600.00
6	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$	1,500.00 400
	Total labour:	\$	3,840.00
	Total parts:	S	9,992.48
	Total labour :	S	3,840.00
	Total repair cost:	\$	13,832.48

Achin Co 1/5 17/09/24 05000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: