

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile MS_LIBERTY_INSURANCE_PTE_LTD Ref: CS/LIP24090311/Unh3m4 | | | | | |
|---|--|---------------------------------|------------------|--------------------------------|--|
| MS | | | | CS/LIP24090311/Unh3m4 | |
| | ONE RAFFLES QUI SINGAPORE 04858 | UAY #25-01 NORTH TOWER 583 | Date: | 05/11/2024 | |
| | ON OAL ONE 04000 | | Code: | LIP | |
| 1. | 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | GW 5H | Veh. Inspected | SND 8201Y | |
| | Policy No. | - | Coverage | 0 | |
| | Claim No. | AVS24/2861 | Excess | \$0.00 | |
| | Assign From | ANDY SEAH | Assign Date | 17/09/2024 | |
| 2. | 2. Vehicle Details | | | | |
| | Make & Model | MITSUBISHI ATTRAGE 1.2 CVT | C.C | 1193 | |
| | Engine No. | 3A92UKH2264 | Year of Reg. | 26/01/2022 | |
| | Chassis No. | MMBSTA13ANH002115 | Colour | RED | |
| | Odometer | 47522 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | General | GOOD | |
| | Modification(s) | RIMS: SPORTS RIM | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | Balance (mm) | |
| | R/H Front Tyre | 185/55R15 | DUNLOP | 6 | |
| | L/H Front Tyre | 185/55R15 | DUNLOP | 6 | |
| | R/H Rear Tyre | 185/55R15 | DUNLOP | 6 | |
| | L/H Rear Tyre | 185/55R15 | DUNLOP | 6 | |
| 4. | 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | | |
| DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | |
| | Accident Date | 14/09/2024 | Inspection Date | 18/09/2024 | |
| | Survey held at | WE GARAGE - 1 KAKI BUKIT AVE 6, | #02-11 AUTOBAY (| © KAKI BUKIT, SINGAPORE 417883 | |
| 5a. Remarks | | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. Estimate Days of Repair | | | | | |
| | | | | | |

ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days