



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: RAJESWARY

Ref: CS/INC24090321/Avh3e2(N)

Date: 05/02/2025

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                |                |            |
|--------------|----------------|----------------|------------|
| Insured Veh. | GBG 5972B      | Veh. Inspected | GBE 1920M  |
| Policy No.   |                | Coverage (\$)  | 0.00       |
| Claim No.    | MT/1295376-002 | Excess (\$)    | 0.00       |
| Assign From  | RAJESWARY      | Assign Date    | 18/09/2024 |

#### 2. Vehicle Particulars & Condition

|              |               |              |          |
|--------------|---------------|--------------|----------|
| Make & Model | TOYOTA DYNA   | c.c          | 2982     |
| Engine No.   | HIDDEN        | Year of Reg. | 2015     |
| Chassis No.  | KDY2318018256 | Colour       | BLUE     |
| Odometer     | 232096 KM     | Steering     | IN ORDER |
| Brakes       | IN ORDER      | Modification | NIL      |
| General      | GOOD          |              |          |

#### 3. Conditions of Tyres

|                | Size     | Make     | Balance |
|----------------|----------|----------|---------|
| R/H Front Tyre | 195 R15C | TRIANGLE | 6 mm    |
| L/H Front Tyre | 195 R15C | TRIANGLE | 6 mm    |
| R/H Rear Tyre  | 165 R13C | TRIANGLE | 6 mm    |
| L/H Rear Tyre  | 165 R13C | TRIANGLE | 6 mm    |

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

#### 5. General Information

|                |  |                     |                         |
|----------------|--|---------------------|-------------------------|
| Accident Date  | 16/09/2024   | Inspect Date / Time | 20/09/2024 ( 04:06 PM ) |
| Survey held at | KT MOTORWERK<br>3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E,<br>SINGAPORE 489978 |                     |                         |

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**