

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24090324/UUA3Q2**Date:** 10/12/2024REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MCV0005041
Claimant Vehicle No : SMH5288H **Insured Vehicle No :** GBF1865J
 Date of Loss: 18/09/2024 Nature of Claim: TP Claim No: MCV2024D0010757

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH5288H**
 Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A) Engine No: LEB7103422
 Reg. Date: 25/01/2019 (Man. Year: 2018) Chassis No: GP72002595
 Colour: White Odometer: 495814 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,204.24	5,794.12	6,410.12	52.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,130.00	1,730.00	2,400.00	58.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,334.24	7,524.12	8,810.12	53.94
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	16,334.24	6,000.00	10,334.24	63.27
+ GST 9.00/9.00% (S\$)	1,470.08	540.00	930.08	63.27
Nett Amount (S\$)	17,804.32	6,540.00	11,264.32	63.27
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		7,267.25		

INSPECTION

Date of Assignment: 19/09/2024
 Date Inspected: 19/09/2024 Inspected At: SPEEDWERKZ PTE LTD (Autobay) (HQ)
 1 KAKI BUKIT AVENUE 6 #01-73
 Singapore 417883
 Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 Oct 2024)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH5288H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,522.50 FL	*1,193.00 FL
2	1		*TAILGATE H LOGO	Necessary	52.10 FL	*52.10 FL
3	1		*TAILGATE SHUTTLE EMBLEM	Necessary	68.30 FL	*68.30 FL
4	2		*TAILGATE HINGES L/R	Not Necessary	188.80 FL	*- FL
5	2		*TAILGATE NUMBER PLATE LAMP L/R	Not Necessary	146.60 FL	*- FL
6	1		*TAILGATE OUTER GARNISH	Cut / Cracked	342.80 FL	*342.80 FL
7	1		*TAILGATE OUTER GARNISH CHROME	Cut	143.70 FL	*143.70 FL
8	2		*TAILGATE SHOCK ABSORBER L/R	Not Necessary	416.20 FL	*- FL
9	2		*TAILGATE LAMP L/R	Cracked	996.60 FL	*770.00 FL
10	1		*TAILGATE OUTER HANDLE	Not Necessary	241.30 FL	*- FL
11	1		*TAILGATE INNER HANDLE POCKET	Not Necessary	79.60 FL	*- FL
12	1		*TAILGATE INNER LOCK	Bent	218.20 FL	*218.20 FL
13	1		*TAILGATE STRIKER	Not Necessary	56.00 FL	*- FL
14	1		*TAILGATE WEATHERSTRIP	Twisted	198.70 FL	*198.70 FL
15	1		*TAILGATE WINDSCREEN MOULDING	Necessary	86.30 FL	*86.30 FL
16	1		*TAILGATE INNER TRIMBOARD	Deformed / Torn	379.30 FL	*379.30 FL
17	1		*TAILGATE INNER PULL POCKET	Not Necessary	78.90 FL	*- FL
18	1		*TAILGATE WIPER MOTOR	Not Necessary	528.00 FL	*- FL
19	2		*TAIL LAMP L/R	Cracked	1,256.80 FL	*960.00 FL
20	1		*REAR BUMPER	Dented	1,268.10 FL	*936.00 FL
21	1		*REAR BUMPER TOW COVER	Not Necessary	86.30 FL	*- FL
22	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	86.00 FL	*- FL
23	2		*REAR BUMPER SIDE BRACKET L/R	Not Necessary	79.60 FL	*- FL
24	1		*REAR BUMPER TOP CHROME	Not fitted	186.90 FL	*- FL
25	1		*REAR BUMPER SPONGE	Not Necessary	128.10 FL	*- FL
26	2		*REAR BUMPER REFLECTORS L/R	Not Necessary	196.80 FL	*- FL
27	2		*REAR BUMPER REFLECTOR GARNISH L/R	Not Necessary	246.40 FL	*- FL
28	1		*REAR BUMPER BUZZER	Not Necessary	96.40 FL	*- FL
29	1		*REAR BUMPER ANTENNA	Not Necessary	162.70 FL	*- FL
30	1		*END PANEL	Dented / Bent	682.70 FL	*517.00 FL
31	1		*END PANEL GARNISH	Twisted	202.10 FL	*202.10 FL
32	1		*REAR FENDER INNER TRIMBOARD L/R	N/S Serviceable / O/S Torn	986.20 FL	*425.80 FL
33	1		*FLOOR PANEL	Repair	1,352.30 FL	*- FL
34	1		*FLOOR PANEL COMPARTMENT TOP COVER	Not Necessary	586.90 FL	*- FL
35	1		*FLOOR PANEL COMPARTMENT TRAY	Cracked	305.60 FL	*305.60 FL
36	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	89.00 FL	*- FL
37	1		*SET REAR REVERSE SENSOR	Malfunction	300.00 FS	*200.00 FS
38	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
39	1		*REAR BUMPER STICKER (KIV)	Necessary	180.00 FS	*- FS
40	1		*SET TAILGATE TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
41	1		*TAILGATE OUTER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
42	1		*TAILGATE STICKER (KIV)	Necessary	200.00 FS	*- FS
43	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
44	1		*TAILGATE WINDSCREEN SPONGE	Necessary	60.00 FS	*20.00 FS
45	1		*END PANEL GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
46	1		*END PANEL SEALANT	Not Necessary	100.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR NUMBER PLATE WITH GARNISH	Damaged	70.00 FS	*35.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (S\$)	14,952.80
					7,153.90	
					- List Item Discount on L Items 20.00/20.00% (S\$)	2,748.56
						1,359.78
					Total Parts (S\$)	12,204.24
						5,794.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR WIRING	New	50.00	20.00
2	TO REPLACE REAR REVERSE SENSOR	New	80.00	30.00
3	TO REMOVE AND REFIT REAR REVERSE CAMERA	New	100.00	0.00
4	TO REMOVE AND TRANSFER TAILGATE FITTINGS TO NEW	New	100.00	50.00
5	TO REMOVE AND REFIT REAR WINDSCREEN	New	180.00	120.00
6	TO REMOVE AND REPLACE REAR INTERIOR TRIMS AND GARNISH	New	120.00	60.00
7	TO PROVIDE LABOUR WORKMANSHIP	New	1,600.00	600.00
8	TO SPRAY PAINT ON AFFECTED PANELS	New	1,600.00	800.00
9	RUST PROOFING	New	150.00	50.00
10	TO REMOVE AND REPLACE REAR EXHAUST MUFFLER	New	150.00	0.00
Gross Labour Cost (\$\$)			4,130.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >