



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO VBK 6556

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT WIND SHIELD	NOT NECESSARY	\$176.00	\$0.00
1	HEAD LAMP COWLING	CRACKED	\$150.00	\$150.00
1	HEAD LAMP STAY	NOT NECESSARY	\$85.00	\$0.00
1	HEAD LAMP COWLING INNER	DEFORMED	\$110.00	\$110.00
1	FRONT MASTER BRAKE PUMP AND RESERVOIR	NOT NECESSARY	\$176.00	\$0.00
1	FRONT HANDLE BAR	NOT NECESSARY	\$380.00	\$0.00
1	HANDLE BAR GRIP	NOT NECESSARY	\$85.00	\$0.00
1	HANDLE BAR BALANCER	CUT	\$48.00	\$48.00
1	SET BRAKE LEVER	CUT	\$180.00	\$50.00
1	SIDE VIEW MIRROR	CUT	\$185.00	\$40.00
1	FRONT HEAD LAMP	CUT	\$480.00	\$480.00
1	FRONT SIGNAL LAMP	MISSING	\$280.00	\$105.00
1	FRONT FORK	BENT	\$850.00	\$760.00
1	FRONT FORK UNDER BRACKET	DAMAGED	\$250.00	\$120.00
1	FRONT FORK RISER	NOT NECESSARY	\$180.00	\$0.00
1	FRONT CAST WHEEL	NOT NECESSARY	\$650.00	\$0.00
1	FRONT WHEEL SHAFT	NOT NECESSARY	\$85.00	\$0.00
1	FRONT DISC PLATE	NOT NECESSARY	\$250.00	\$0.00
1	COVER SET COMPLETE SET	CRACKED	\$850.00	\$600.00
1	COVERT SET INNER COMPLETE SET	DAMAGED	\$650.00	\$380.00
1	PILLION STEP PADAL	NOT NECESSARY	\$85.00	\$0.00
1	RADIATOR ASSY	NOT NECESSARY	\$550.00	\$0.00
1	REAR TAIL LAMP	CUT	\$440.00	\$140.00
1	REAR EXHAUST MUFFLE	NOT NECESSARY	\$680.00	\$0.00
1	REAR EXHAUST COVER	CUT	\$140.00	\$100.00
1	REAR FENDER	NOT NECESSARY	\$198.00	\$0.00
1	REAR LICENSE PLATE LAMP	CRACKED	\$50.00	\$50.00
1	REAR REFLECTOR	NOT NECESSARY	\$35.00	\$0.00
1	REAR FENDER BRACKET	NOT NECESSARY	\$48.00	\$0.00
1	REAR SLIDER	CUT	\$120.00	\$70.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR MUDGUARD	NOT NECESSARY	\$258.00	\$0.00
1	REAR SIGNAL LAMP	NOT NECESSARY	\$98.00	\$0.00
1	REAR PILLION HANDLE	TO REPAIR SEE LABOUR	\$148.00	\$0.00
1	REAR FOOT REST PADAL	NOT NECESSARY	\$105.00	\$0.00
1	FRONT LEG SHIELD (NPA)	NOT NECESSARY	\$0.00	\$0.00
	LESS 10.00% DISCOUNT		(\$905.50)	(\$320.30)
			\$8,149.50	\$2,882.70

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR ABSORBER (SN)	NOT NECESSARY	\$1,850.00	\$0.00
1	FRONT BRAKE DISC MOUNTING BOLTS (SN)	NOT NECESSARY	\$15.00	\$0.00
1	CALIPER MOUNTING BOLTS (SN)	NOT NECESSARY	\$15.00	\$0.00
1	FRONT BRAKE MASTER PUMP BOLTS (SN)	NOT NECESSARY	\$15.00	\$0.00
1	FRONT FENDER MOUNTING (SN)	NOT NECESSARY	\$15.00	\$0.00
1	FRONT COWLING MOUNTING BOLTS AND NUTS (SN)	NOT NECESSARY	\$15.00	\$0.00
1	RADIATOR MOUNTING BOLTS (SN)	NOT NECESSARY	\$15.00	\$0.00
1	EMBLEM (SN)	NECESSARY	\$50.00	\$50.00
1	STEP PAD (SN)	NOT NECESSARY	\$95.00	\$0.00
			\$2,085.00	\$50.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR TO REMOVE AND REPLACE AFFECTED COMPONENTS. INCLUSIVE OF THE REPAIR OF REAR PILLION HANDLE		\$500.00	\$250.00
	SPRAY PAINT		\$600.00	\$250.00
	CHASSIS ALIGNMENT	NOT NECESSARY	\$500.00	\$0.00
			\$1,600.00	\$500.00

GRAND TOTAL			\$11,834.50	\$3,432.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$2,700.00

Report Ref No: CS/SMO24090328/Aqp3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.