



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

|                                       |       |                       |
|---------------------------------------|-------|-----------------------|
| MS SOMPO INSURANCE SINGAPORE PL       | Ref:  | CS/SMO24090328/Aqp3e2 |
| 50 RAFFLES PLACE #03-03               | Date: | 08/11/2024            |
| SINGAPORE LAND TOWER SINGAPORE 048623 | Code: | SMO                   |

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                 |                |            |
|--------------|-----------------|----------------|------------|
| Insured Veh. | FBS 8024E       | Veh. Inspected | VBK 6556   |
| Policy No.   | -               | Coverage       | 0          |
| Claim No.    | CMTD2402990/JYC | Excess         | \$0.00     |
| Assign From  | JIA YI          | Assign Date    | 17/09/2024 |

### 2. Vehicle Details

|                 |                   |              |            |
|-----------------|-------------------|--------------|------------|
| Make & Model    | YAMAHA XMAX       | C.C          | 250        |
| Engine No.      | G3H5E0014653      | Year of Reg. | 22/05/2023 |
| Chassis No.     | PMYSG4020P0005653 | Colour       | BLACK      |
| Odometer        | 42087 KM          | Steering     | IN ORDER   |
| Brakes          | IN ORDER          | General      | GOOD       |
| Modification(s) | RIMS: SPORTS RIM  |              |            |

### 3. Conditions of Tyres

|                |            |        |              |
|----------------|------------|--------|--------------|
|                | Size       | Make   | Balance (mm) |
| R/H Front Tyre | 120/70 R15 | MAXXIS | 6            |
| L/H Front Tyre |            |        |              |
| R/H Rear Tyre  | 140/70 R14 | MAXXIS | 6            |
| L/H Rear Tyre  |            |        |              |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION AND O/S BODY.

DAMAGES SEE DETAILS.

### 5. General Information

|                |   |                 |            |
|----------------|---|-----------------|------------|
| Accident Date  | 12/09/2024  | Inspection Date | 18/09/2024 |
| Survey held at | APEX MOTORWORKS - 2 KAKI BUKIT AVENUE 2 AUTOHUB #01-14 SINGAPORE 417921 |                 |            |

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days