



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

| | | |
|--|-------|---------------------|
| MS AUTO & GENERAL INSURANCE (S) PL | Ref: | CS/AGI24090329/Uqp3 |
| (BUDGET DIRECT INSURANCE) | Date: | 17/10/2024 |
| 190 CLEMENCEAU AVENUE #03-01 | Code: | AGI |
| SINGAPORE SHOPPING CENTRE SINGAPORE 239924 | | |

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|---------------|----------------|------------|
| Insured Veh. | SJP 626S | Veh. Inspected | SMF 4166T |
| Policy No. | P10796626R02 | Coverage | 0 |
| Claim No. | C10031751/CH | Excess | \$0.00 |
| Assign From | LAN BOON CHIN | Assign Date | 18/09/2024 |

2. Vehicle Details

| | | | |
|-----------------|----------------------|--------------|------------|
| Make & Model | SKODA KODIAQ 2.0 (A) | C.C | 1984 |
| Engine No. | CZP161331 | Year of Reg. | 09/11/2018 |
| Chassis No. | TMBMD9NS3J8096312 | Colour | BLACK |
| Odometer | 93434 KM | Steering | IN ORDER |
| Brakes | IN ORDER | General | GOOD |
| Modification(s) | RIMS: SPORTS RIM | | |

3. Conditions of Tyres

| | Size | Make | Balance (mm) |
|----------------|-----------|----------|--------------|
| R/H Front Tyre | 255/45R20 | MICHELIN | 7 |
| L/H Front Tyre | 255/45R20 | MICHELIN | 7 |
| R/H Rear Tyre | 255/45R20 | MICHELIN | 7 |
| L/H Rear Tyre | 255/45R20 | MICHELIN | 7 |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 17/09/2024 | Inspection Date | 18/09/2024 |
| Survey held at | LEE BROTHERS AUTOMOTIVE PTE LTD - 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883 | | |

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days