



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL	Ref:	CS/SMO24090331/Kvp3m4
50 RAFFLES PLACE #03-03	Date:	08/10/2024
SINGAPORE LAND TOWER SINGAPORE 048623	Code:	SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GU 1064R	Veh. Inspected	SKN 600P
Policy No.	-	Coverage	0
Claim No.	CMTD2402989/SYH	Excess	\$0.00
Assign From	SHIANG YI	Assign Date	18/09/2024

2. Vehicle Details

Make & Model	TOYOTA HARRIER (A)	C.C	1998
Engine No.	8ARZ120275	Year of Reg.	08/06/2018
Chassis No.	JTEKB3GH00J002059	Colour	METALLIC BLACK
Odometer	136398 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/60R18	BRIDGESTONE	3
L/H Front Tyre	225/60R18	BRIDGESTONE	3
R/H Rear Tyre	225/60R18	BRIDGESTONE	2
L/H Rear Tyre	225/60R18	BRIDGESTONE	2

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/09/2024	Inspection Date	18/09/2024
Survey held at	OPTIMA WERKZ PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days