

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24090332/RMA3Q2

Date: 18/10/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0000111_05
Claimant Vehicle No : SMZ8845K Insured Vehicle No : PC7966L
Date of Loss: 03/09/2024 Nature of Claim: TP Claim No: MFL2024D0010399

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMZ8845K
Make & Model: HYUNDAI IONIQ EV, (A) Engine No: HIDDEN
Reg. Date: 24/05/2021 (Man. Year: 2021) Chassis No: KMHC851JUMU079037
Colour: Grey Odometer: 53017 km
Engine Capacity: 0 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,711.20	3,508.00	2,203.20	38.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,890.00	2,350.00	4,540.00	65.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	12,601.20	5,858.00	6,743.20	53.51
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 23/09/2024
Date Inspected: 23/09/2024 Inspected At: Komoco Motors Pte Ltd (HQ)
253 ALEXANDRA ROAD, #01-01
Singapore 159936
Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Oct 2024)
Parts:	192	HYUNDAI IONIQ EV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMZ8845K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER CLIP	Necessary	20.00 FL	*20.00 F
2	1		*COVER -FR BUMPER	Deformed	554.00 FL	*554.00 F
3	1		*MOULDING -FRONT BUMPER CTR UPR	Scratched	139.00 FL	*139.00 F
4	1		*MOULDING -FRONT BUMPER LH	Scratched	55.00 FL	*55.00 F
5	1		*LAMP ASSY -DAY RUNNING LIGHT LH	*Check	643.00 FL	*- F
6	1		*BRACKERT -FR BUMPER SIDE LH	Necessary	20.00 FL	*20.00 F
7	1		*PANEL FENDER LH	Bent	589.00 FL	*589.00 F
8	1		*LAMP ASSY -HEAD LH	Cracked	2,111.00 FL	*2,111.00 F
9	1		*REINF-FENDER APRON UPR LH	*Check	130.00 FL	*- F
10	1		*BEAM COMPLETE-FR BUMPER	*Check	1,484.00 FL	*- F
11	1		*CARRIER ASSY -FRONT END MODULE	*Check	950.00 FL	*- F
12	1		*BRACKET ASSY -FENDER MTG FR LH	Not Necessary	42.00 FL	*- F
13	1		*BRACKET ASSY -FENDER MTG FR RH	Not Necessary	42.00 FL	*- F
14	1		*MOULDING ASSY SIDE SILL LH	*Check	310.00 FL	*- F
15	1		*SUNDRIES	Necessary	40.00 FS	*20.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (\$\$)					7,129.00	3,508.00
- List Item Discount on L Items 20.00/0.00% (\$\$)					1,417.80	0.00
Total Parts (\$\$)					5,711.20	3,508.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CARRY OUT ACCIDENT BODY REPAIR -FRT BUMPER /FRT LH FENDER /SUPPORT PANEL	New	2,760.00	920.00
2	COMPLETE PUTTY AND SPRAY PAINT ALL AFFECTED AREAS -FRT BUMPER /FRT LH FENDER /FRT LH BUMPER GARNISH CTR/FRONT BUMPER MOULDING LHS	New	1,750.00	1,050.00
3	TO REALIGN FRT BOTH HEADLAMP	New	40.00	20.00
4	TO REPAIR FRT LH FENDER APRON (*Check)	New	460.00	0.00
5	TO TOP UP A/C GAS	New	140.00	0.00
6	TO REPAIR FRT CHASSIS MEMBER	New	460.00	0.00
7	TO RECALIBRATE FRT RADAR SENSOR	New	460.00	0.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNTIONING AFTER ACCIDENT REPAIR	New	180.00	180.00
9	TO PERFORM PREPROGRAMME AFTER ACCIDENT REPAIR	New	180.00	180.00
10	TO R & I FRT LH SIDE SILL TO FACILITATE REPAIR (*Check)	New	460.00	0.00
Gross Labour Cost (\$\$)			6,890.00	2,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >