

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24090333/UNP3E2
Date: 14/11/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	FBW2434Z	Insured Vehicle No :	SKP6204A
Date of Loss:	11/09/2024	Nature of Claim:	TP
		Claim No:	DMPC2401219H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBW2434Z	Engine No:	RH10E5050778
Make & Model:	HONDA ADV750, 745cc ABS AUTO	Chassis No:	JH2RH10A9RK309456
Reg. Date:	21/03/2024 (Man. Year: 2023)	Odometer:	2318 km
Colour:	Blue		
Engine Capacity:	745 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70 R17	Rear Tyre Size:	160/60 R15
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,172.40	1,735.00	1,437.40	45.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	280.00	200.00	80.00	28.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	3,452.40	1,935.00	1,517.40	43.95

INSPECTION

Date of Assignment:	18/09/2024	
Date Inspected:	18/09/2024	Inspected At: Teo Spray Painting (HQ) BLK 6 DEFU LANE 10, DEFU IND PARK C #01-558 Singapore 539187
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 14 Nov 2024)	
Parts:	N/A	HONDA ADV750 745cc ABS AUTO (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBW2434Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FOOTBOARD LH	Cut	160.00 FL	*160.00 FL
2	1		*LOWER SIDE COVER LH	Cut	300.00 FL	*300.00 FL
3	1		*SIDE MIRROR	Cut	140.00 FL	*140.00 FL
4	1		*HAND GUIDE	Cut	80.00 FL	*80.00 FL
5	1		*BRAKE LEVER	Bent	95.00 FL	*95.00 FL
6	1		*PILLION BAR LH	Cut	260.00 FL	*260.00 FL
7	1		*HANDLE BAR	Bent / Jammed	480.00 FL	*480.00 FL
8	1		*EXHAUST PIPE	Repair	1,486.00 FL	*- FL
9	1		*REAR LICENCE PLATE	Bent	20.00 FS	*20.00 FS
10	1		*HAND GUIDE SCREW	Cut	35.00 FL	*35.00 FL
11	1		*EXHAUST CARBON COVER	Cracked	420.00 FS	*320.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (S\$)	3,476.00 1,890.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	303.60 155.00
					Total Parts (S\$)	3,172.40 1,735.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES	New	280.00	200.00
Gross Labour Cost (S\$)			280.00	200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >