



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGS SINGAPORE 048581 ATTN: AINI		Ref: CS/FCI24090334/Tvp3e2(N) Date: 14/01/2025 Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHD 4260Z	Veh. Inspected	SLC 9468S
Policy No.	D-24101861MFCT	Coverage (\$)	0.00
Claim No.	D24008126MFCT	Excess (\$)	0.00
Assign From	AINI	Assign Date	18/09/2024
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HONDA ODYSSEY	c.c	2354
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JHMRB18507C203869	Colour	ORANGE
Odometer	194150 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	DUNLOP	6 mm
L/H Front Tyre	215/55 R17	DUNLOP	6 mm
R/H Rear Tyre	215/55 R17	DUNLOP	6 mm
L/H Rear Tyre	215/55 R17	DUNLOP	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION, O/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	15/09/2024	Inspection Date	18/09/2024
Survey held at	60 JALAN LAM HUAT #04-53 S 737869		
Repairer	WIN AUTOMOTIVE SERVICES		
<b>5a. Remarks</b>			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	