

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24090337/UUA3Q2**Date:** 19/12/2024**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900169111
Claimant Vehicle No : PC3806S **Insured Vehicle No :** SLT9356S
 Date of Loss: 10/09/2024 Nature of Claim: TP Claim No: 6510126598SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC3806S**
 Make & Model: TOYOTA HIACE, 2.8 D COMMUTER GL (A) Engine No: 1GD8863984
 Reg. Date: 08/07/2022 (Man. Year: 2022) Chassis No: GDH2232004243
 Colour: Silver Odometer: 166414 km
 Engine Capacity: 2754 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
 Front Left Side: Agilis 6 mm Rear Left Side: Agilis 6 mm
 Front Right Side: Agilis 6 mm Rear Right Side: Agilis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,503.32	4,002.52	2,500.80	38.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,970.00	750.00	1,220.00	61.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,473.32	4,752.52	3,720.80	43.91
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	8,473.32	3,800.00	4,673.32	55.15
+ GST 9.00/9.00% (S\$)	762.60	342.00	420.60	55.15
Nett Amount (S\$)	9,235.92	4,142.00	5,093.92	55.15
+ Car Rental (5.0 x S\$100.00/day + 9.00% GST) (S\$)		545.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		4,689.18		

INSPECTION

Date of Assignment: 20/09/2024
 Date Inspected: 20/09/2024 Inspected At: Stytech Auto Pte Ltd (HQ)
 2 Kaki Bukit Ave 2 #02-30, Kaki Bukit Autohub
 Singapore 417921
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	788.20 FL	*788.20 FL
2	1		*FRONT BUMPER SIDE HOLDER N/S	Serviceable	217.70 FL	*- FL
3	1		*SET FRONT BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
4	1		*FRONT FOG LAMP COVER N/S	Twisted	96.90 FL	*96.90 FL
5	1		*HEADLAMP LED N/S	Cracked	3,668.20 FL	*3,668.20 FL
6	1		*FRONT CORNER PANEL N/S	Dented / Bent	455.20 FL	*455.20 FL
7	1		*FRONT DOOR N/S	Repair	1,866.20 FL	*- FL
8	1		*FRONT STEP PANEL GARNISH N/S	Cut	283.20 FL	*283.20 FL
9	1		*FRONT STEP PANEL N/S	Repair	350.50 FL	*- FL
10	1		*FRONT VIDEO CAM ASSY N/S	Serviceable	900.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	8,671.10	5,336.70
- List Item Discount on L Items 25.00/25.00% (\$)	2,167.78	1,334.18
Total Parts (\$)	6,503.32	4,002.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	120.00	30.00
3	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	800.00	350.00
4	TO SPRAY PAINTING	New	1,000.00	350.00
Gross Labour Cost (\$\$)			1,970.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >