



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SML 9430R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	DENTED	\$658.00	\$549.00
1	REAR BUMPER SIDE RETAINER LH	BROKEN	\$112.00	\$112.00
1	REAR BUMPER LIP	DEFORMED	\$728.90	\$380.00
1	REAR FENDER LH	NOT NECESSARY	\$698.00	\$0.00
1	TAILAMP LH	NOT NECESSARY	\$598.00	\$0.00
	<b>LESS 20.00 / 25.00% DISCOUNT</b>		(\$558.98)	(\$260.25)
			<b>\$2,235.92</b>	<b>\$780.75</b>
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER CLIPS (SN)	NECESSARY	\$50.00	\$30.00
1	REVERSE SENSOR (SN)	SHORTED	\$200.00	\$200.00
			<b>\$250.00</b>	<b>\$230.00</b>
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK REAR ELECTRICAL WIRING		\$80.00	\$30.00
	TO REMOVE AND RENEW REVERSE SENSOR		\$100.00	\$30.00
	SPRAY PAINTING ON AFFECTED AREAS		\$500.00	\$200.00
	PANEL BEATING ON AFFECTED AREAS		\$400.00	\$200.00
			<b>\$1,080.00</b>	<b>\$460.00</b>
<b>GRAND TOTAL</b>			<b>\$3,565.92</b>	<b>\$1,470.75</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>\$1,200.00</b>
Report Ref No: CS/FCI24090339/Evp3m4				

**CTY**

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.