



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SML 7843X

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	DENTED	\$1,825.70	\$595.00
10	REAR BUMPER CLIPS	NECESSARY	\$100.00	\$30.00
1	REAR BUMPER SIDE RETAINER - LH	DENTED	\$146.20	\$60.00
1	REAR BUMPER SIDE RETAINER - RH	DENTED	\$146.20	\$60.00
1	REAR BUMPER LAMP - RH	NOT NECESSARY	\$368.50	\$0.00
1	REAR FENDER - RH	TO REPAIR SEE LABOUR	\$1,750.70	\$0.00
1	REAR FENDER ARCH GARNISH - RH	NOT NECESSARY	\$498.50	\$0.00
1	REAR FENDER DUST COVER - RH	NOT NECESSARY	\$385.20	\$0.00
1	REAR DOOR - RH	NOT NECESSARY	\$1,425.60	\$0.00
1	REAR DOOR ARCH GARNISH - RH	NOT NECESSARY	\$498.50	\$0.00
1	REAR SHOCK ABSORBER - RH	NOT NECESSARY	\$698.50	\$0.00
1	REAR AXLE BEAM	NOT NECESSARY	\$3,285.70	\$0.00
1	REAR WHEEL BEARING - RH	NOT NECESSARY	\$358.20	\$0.00
1	REAR FENDER INNER GARNISH - RH	NOT NECESSARY	\$725.20	\$0.00
1	REAR FENDER AIR DUST - RH	NOT NECESSARY	\$175.00	\$0.00
1	REAR END PANEL	NOT NECESSARY	\$1,150.10	\$0.00
1	REAR TAILLAMP - RH	NOT NECESSARY	\$725.50	\$0.00
	<b>LESS 0.00 / 20.00% DISCOUNT</b>		\$0.00	(\$149.00)
			\$14,263.30	\$596.00

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR WHEEL RIM - RH (SN)	SLICED	\$1,200.00	\$300.00
1	REAR TYRE - RH (SN)	NOT NECESSARY	\$350.00	\$0.00
			\$1,550.00	\$300.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY. INCLUSIVE OF THE REPAIR OF REAR FENDER - RH		\$1,800.00	\$300.00
	TO SUPPLY PAINTING MATERIAL }		\$600.00	\$400.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION }		\$1,800.00	\$0.00
	TO APPLY RUST - PROOFING ON REPAIRED, REPLACED PANEL		\$220.00	\$20.00
	TO WHEEL ALIGNMENT		\$280.00	\$80.00
	TO REMOVE/RENEW L/H REAR UNDERCARRIAGE	NOT NECESSARY	\$600.00	\$0.00
	TO COMPUTER RESET	NOT NECESSARY	\$650.00	\$0.00
	TO CHECK WIRING FUNCTIONS		\$150.00	\$30.00
			\$6,100.00	\$830.00
<b>GRAND TOTAL</b>			<b>\$21,913.30</b>	<b>\$1,726.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>\$1,350.00</b>
<b>Report Ref No: CS1/LPM24090342/Enh3</b>				

**CTY**

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.