

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24090346/UPA3Q2**Date:** 07/07/2025REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100459322
Claimant Vehicle No :	JTL5352	Insured Vehicle No :	SLB2502C
Date of Loss:	01/09/2024	Nature of Claim:	TP
		Claim No:	7492643269SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JTL5352	Engine No:	G401E0086014
Make & Model:	YAMAHA YZF-R25, 250cc	Chassis No:	PMYRG1520K0001200
Reg. Date:	11/06/2019 (Man. Year: 2019)	Odometer:	84976 km
Colour:	Blue		
Engine Capacity:	250 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120-70-17	Rear Tyre Size:	130-70-17
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,162.70	5,138.20	5,024.50	49.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,110.00	380.00	730.00	65.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,272.70	5,518.20	5,754.50	51.05
Approved Total (Overridden) (S\$)		4,400.00		
Nett Amount (S\$)	11,272.70	4,400.00	6,872.70	60.97
+ Loss of Use (5.0 x S\$10.00/day) (S\$)		50.00		
+ Other Costs (S\$)		40.00		
Nett Liability (S\$)		4,490.00		
Global Sum Settlement (S\$)		4,450.00		

INSPECTION

Date of Assignment:	19/09/2024	
Date Inspected:	19/09/2024	Inspected At: Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62 Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FORK TUBE ASSY -L/H	Serviceable	980.00 FL	*- FL
2	1		*FORK TUBE ASSY -R/H	Damaged / Dented	980.00 FL	*800.00 FL
3	1		*FORK UNDER BRACKET	Twisted	480.00 FL	*325.00 FL
4	1		*FRONT RIM	Not Necessary	385.00 FL	*- FL
5	1		*FRONT RIM SHAFT	Not Necessary	120.00 FL	*- FL
6	1		*FRONT RIM BEARING	Not Necessary	90.00 FL	*- FL
7	1		*HEADLAMP ASSY	Cracked	980.00 FL	*600.00 FL
8	1		*HEADLAMP COVER	Cut	180.00 FL	*145.00 FL
9	1		*LAMPSTAY	Bent	380.00 FL	*200.00 FL
10	1		*FRONT TOP INNER COVER	Cut	110.00 FL	*110.00 FL
11	1		*FRONT SIDE INNER COVER -MATT	Cracked	165.00 FL	*165.00 FL
12	1		*HANDLE-BAR -L/R/H	Bent	400.00 FL	*280.00 FL
13	1		*HAND GRIP	Torn	88.00 FL	*88.00 FL
14	1		*HANDLE BAR END	No such part	110.00 FL	*- FL
15	2		*MIRROR -L/R/H	Cut	360.00 FL	*190.00 FL
16	1		*SET FRONT SIGNAL	Cracked	150.00 FL	*100.00 FL
17	1		*GEAR PEDAL	Cut	165.00 FL	*115.00 FL
18	1		*BRAKE PEDAL	Repair	180.00 FL	*- FL
19	1		*SET FRONT FOOTREST	Cut	230.00 FL	*160.00 FL
20	1		*FRONT FOOTREST BRACKET	Cut	380.00 FL	*190.00 FL
21	1		*SET REAR FOOTREST	Cut	200.00 FL	*160.00 FL
22	1		*REAR FOOTREST BRACKET -L/H	Cut	250.00 FL	*190.00 FL
23	1		*SET FAIRING ASSY	Cracked	2,800.00 FL	*1,280.00 FL
24	1		*SET NUMBER PLATE	Necessary	38.00 FS	*10.00 FS
25	2		*FORK OILS	Not Necessary	48.00 FS	*- FS
26	2		*FORK OIL SEALS	Not Necessary	100.00 FS	*- FS
27	1		*BEARING CONE	Necessary	120.00 FS	*60.00 FS
28	1		*ENGINE SLIDER	Cut	485.00 FS	*280.00 FS
29	1		*REAR SLIDER	Cut	225.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,179.00	5,648.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,016.30	509.80
Total Parts (\$\$)	10,162.70	5,138.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
2	TO REALIGNMENT BODY FRAME	New	550.00	0.00
3	TO PROVIDE LABOUR	New	480.00	380.00
Gross Labour Cost (\$\$)			1,110.00	380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >