

JSA 9700

Rear Bootlid
 " hinge x2 @97.40
 " outer midg
 " lock
 " Stricker
 " logo
 " Vias logo
 " X logo
 " marker strip
 Tail lamp Assy x2 @445.80
 " panel
 " garnish

R1 @852.40 —
 R @194.80 X
 CM/nd @201.40 —
 R1 @198.60 —
 R @29.90 X
 M @57.00 —
 MC @61.00 —
 M @57.00 —
 nd/di @166.40 508in 83.20in
 CM @891.60 —
 M @710.20 —
 M/di @198.70 —

Rear bumper Assy
 " retain x2 @131.90
 " reinforcement
 " reverse sensor
 " clips
 Rear Bumper Kit

RVC @565.00 —
 CM @263.80 —
 R @322.30 X
 S @300.00SN X
 M @60.00SN —
 R @894.80 X

258

Rear No plate
 " windscreen Sealant

CM @50.00 25SN
 M @40.00 X

Labour

1. To dismantle / renew accident damaged portion. To panel beat, straighten and align replacement parts.
2. To check wiring
3. To rust proof affected portion after repair.

\$1200.00 80d
 \$40.00 20d
 \$100.00 60d

4. To remove & refix rear windscreen NW £150.00 X
5. To remove & refit interior trim, garnish & etc. £150.00 80%
6. Supply spray paint materials & respray affected areas. £1500.00 1000%
7. Remove & refix rear reverse sensor £80.00 50%

Not Authorised
 11/11/11 £4100/-
 Pursuing After Party

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

6 days