

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG24060171/RNP3M4

Date: 01/08/2024

REFERENCE

Insured/Claimant:	JAIN SONAM	Policy No:	1800017636		
Date of Loss:	19/06/2024	Nature of Claim:	OD	Claim No:	3513195811SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW5710M		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK049165
Reg. Date:	22/02/2018 (Man. Year: 2017)	Chassis No:	WAUZZZF4XJA063644
Colour:	Red	Odometer:	37810 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$81,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,218.00	3,514.80	18,703.20	84.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,122.00	2,372.00	2,750.00	53.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,340.00	5,886.80	21,453.20	78.47
- Excess (S\$)	550.00	550.00	0.00	0.00
(S\$)	26,790.00	5,336.80	21,453.20	80.08
+ GST 9.00/9.00% (S\$)	2,411.10	480.31	1,930.79	80.08
Nett Amount (S\$)	29,201.10	5,817.11	23,383.99	80.08

INSPECTION

Date of Assignment:	25/06/2024	
Date Inspected:	25/06/2024	Inspected At: 24 BENOI SECTOR, SINGAPORE 629857 REPAIRER: PREMIUM AUTOMOBILES PTE LTD
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,670.00 FS	*2,136.00 FS
2	1		*FRONT BUMPER FIXING PARTS (TBC) (NPA)	Not Necessary	0.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	90.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	245.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	286.00 FS	*- FS
6	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	160.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,613.00 FS	*1,290.40 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	169.00 FS	*- FS
9	2		*FRONT PARKING AID SENSOR	Not Necessary	572.00 FS	*- FS
10	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	11.00 FS	*- FS
11	1		*FRONT BUMPER TOP COVER	Not Necessary	160.00 FS	*- FS
12	1		*FRONT FOAM FILLER PIECE	Not Necessary	156.00 FS	*- FS
13	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	1,033.00 FS	*- FS
14	1		*OUTSIDE TEMP SENSOR BRACKET	Not Necessary	37.00 FS	*- FS
15	1		*LOCK CARRIER BRACKET	Not Necessary	173.00 FS	*- FS
16	1		*CAUTION STICKER	Not Necessary	25.00 FS	*- FS
17	1		*A/C STICKER	Not Necessary	10.00 FS	*- FS
18	1		*LED HEADLIGHT - LH	Not Necessary	9,325.00 FS	*- FS
19	3		*LED HEADLIGHT SPACER- LH	Not Necessary	150.00 FS	*- FS
20	2		*RADIATOR AIR GUIDE - LH / RH OUTER	Not Necessary	54.00 FS	*- FS
21	1		*LIFT CYLINDER - LH	Not Necessary	252.00 FS	*- FS
22	1		*LIFT CYLINDER BRACKET - LH	Not Necessary	8.00 FS	*- FS
23	1		*BONNET	Repair	3,470.00 FS	*- FS
24	1		*BONNET ATTACHMENT	Not Necessary	460.00 FS	*- FS
25	1		*BONNET IMPACT PROTECTION - CENTER	Cracked	36.00 FS	*28.40 FS
26	2		*BONNET IMPACT PROTECTION - LH / RH	Not Necessary	72.00 FS	*- FS
27	1		*FRONT FENDER LEDGE COVER - LH SHORT	Not Necessary	29.00 FS	*- FS
28	1		*FRONT FENDER LEDGE COVER - LH LONG	Not Necessary	39.00 FS	*- FS
29	2		*BONNET STRIKER - LH / RH	Not Necessary	126.00 FS	*- FS
30	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	80.00 FS	*- FS
31	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	80.00 FS	*- FS
32	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	27.00 FS	*- FS
33	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	40.00 FS	*- FS
34	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
35	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 22,218.00 3,514.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. RE- ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	500.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	1,900.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$\$)			5,122.00	2,372.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >