

# 源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600F

126 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 TWP: 9742 6003

Not Authorized  
L/Sump @ 8.850/hr  
Recovery After Pain  
9 days

## REPAIR ESTIMATE SMH3399J

No.	Qty	Nett Items			
1	1	Front bumper	762-70	\$ CM	947.40 ✓
2	1	Front bumper grille		\$ Sn	385.00 X
3	1	Front bumper LH fog lamp cover		\$ Sn	45.00 X
4	1	Front bumper LH fog lamp		\$ Sn	327.00 X
5	1	Front bumper lower black skirting		\$ Diy	429.00 ✓
6	1	Front bumper LH side retainer		\$ CM	25.00 ✓
7	1	Front bumper inner reinforcement		\$ R	321.00 X
8	1 set	Front bumper clips		\$ Rn	50.00 ✓
9	1	LH headlamp	1917	CMS	2,050.00 ✓
10	1	LH headlamp lower bracket		\$ R	35.00 X
11	1	Front LH fender		\$ R	444.70 ✓
12	1	Front LH fender lower black garnish		\$ Rn	178.00 ✓
13	1 set	Front LH fender lower black garnish clips		\$ Rn	40.00 ✓
14	1	Front LH fender under shield		\$ Diy	129.00 ✓
15	1 set	Front fender under shield clips		\$ Rn	30.00 ✓
16	1	Front LH wheel house panel		\$ R	670.50 X
17	1	Front LH wheel house extension		\$ R	280.00 X
18	1	Front LH side mirror body		\$ Diy	623.00 ✓
19	1	Front LH side mirror cover		\$ R	84.40 X
20	1	Front LH door		\$ Rn	950.00 ✓
21	2	Front LH door hinge (Top & bottom)		\$ R	116.40 X
22	1	Front LH door checker		\$ Sn	85.70 X
23	1	Front LH door weatherstrip		\$ Sn	87.40 X
24	1 set	Front LH door inner trim board clips		\$ Rn	50.00 X
25	2	Front sport rims LH/RH		\$ Rn	1,645.80 ✓
26	2	Front shock absorber LH/RH		\$ Rn	736.00 ✓
27	2	Front lower arm LH/RH		\$ Diy	933.00 ✓
28	2	Front knuckle arm LH/RH		\$ Rn	540.00 ✓
29	1	Front LH drive shaft		\$ R	1,018.70 X
30	1	Front stabilizer bar		\$ Sn	211.70 X
31	1	Front stabilizer bar LH link rod		\$ Sn	107.60 X
32	2	Front wheel hub LH/RH		\$ Rn	510.00 ✓
33	2	Front wheel bearing LH/RH		\$ Rn	300.00 ✓
			208	Total:	\$ 14,386.30
					\$ Tn 220.00 50% in 110\$
					\$ 80.00 60l
1		Towing charges.		\$	80.00 60l
2		Labour Charges for remove/refit, cutting/welding and replacement of damages.		\$	1,600.00 700l
3		To putty and spray Spray Paintings charges.		\$	1,200.00 860l
4		To check wirings and lightings.		\$	40.00 20l
5		To remove, refit front door fittings.		\$	80.00 60l
6		To remove, refix both front under carriages damage parts.		\$	280.00 240l

7	To remove, refit engine & gearbox assy, to facilitate repair	\$	<i>nn</i> 350.00	<i>X</i>
8	To conduct computerise wheel alignment test.	\$	100.00	<i>601</i>
9	To supply and apply anti rust treatment	\$	80.00	<i>601</i>
	<b>Total :</b>	<b>\$</b>	<b>3,810.00</b>	

**Total Parts and Labour : \$ 18,416.30**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

# 源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

19.09.2024

## SUPPLEMENTARY REPAIR ESTIMATE FOR Honda Vezel - SMH 3399 J

List Items  
1 pc. LH Rocker Panel garnish  
1 pc. Front bumper spoiler

*od/w* \$ 320.00 ✓  
*cm* 84.90 ✓  
\$ 404.90  
Less 20% 80.98  
\$ 323.92 \$ 323.92

Special Nett Items  
1 pc. Front RH tyre  
1 set. Front LH mud flap

*1105w* *wt* \$ 220.00 ✓  
*011* \$ 280.00 ✓  
**TOTAL** \$ 823.92

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: