

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI24090351/RVP3M4**Date:** 21/10/2024**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No: DMCG24005485
Claimant Vehicle No : SND6020R **Insured Vehicle No :** GBH3270B
Date of Loss: 09/09/2024 Nature of Claim: TP Claim No: CDMCG24002420

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SND6020R**
Make & Model: BMW 218I, 1.5 GT SPORT LED HL NAV (A) Engine No: 33676618B38A15F
Reg. Date: 13/01/2022 (Man. Year: 2021) Chassis No: WBA6V720105U61631
Colour: Blue Odometer: 39549 km
Engine Capacity: 1499 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R19 Rear Tyre Size: 205/55R19
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,647.20	1,357.35	4,289.85	75.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,231.00	2,325.00	906.00	28.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,878.20	3,682.35	5,195.85	58.52
+ GST 9.00/9.00% (S\$)	799.04	331.41	467.63	58.52
Nett Amount (S\$)	9,677.24	4,013.76	5,663.48	58.52

INSPECTION

Date of Assignment: 18/09/2024
Date Inspected: 07/10/2024 Inspected At: PERFORMANCE MOTORS LIMITED (HQ)
303 ALEXANDRA ROAD,
SINGAPORE 159941
Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$4,770.85 NETT)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2024)
Parts:	M1-MPV	BMW 218I 1.5 GT SPORT LED HL NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SND6020R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	* Check	150.00 FS	*- FS
2	2		*EXPANDING NUT	* Check	1.90 FS	*- FS
3	1		*NECESSARY KIT ON	* Check	73.95 FS	*- FS
4	1		*GRATE CENTRE CLOSED (LINES/PDC)	* Check	170.55 FS	*- FS
5	1		*RH FINISHER	* Check	55.45 FS	*- FS
6	1		*RH MOLDING (SPORT)	* Check	62.55 FS	*- FS
7	1		*IMPACT ABSORBER TOP	* Check	64.00 FS	*- FS
8	1		*TRIM STRIP CENTRE (SPORT)	* Check	55.05 FS	*- FS
9	1		*COVERING CENTER	* Check	76.40 FS	*- FS
10	1		*FRT BUMPER PANEL PRIMED (BASIC)	Deformed	987.80 FS	*987.80 FS
11	1		*RH GRID LATERAL (LINES/PDC)	* Check	102.35 FS	*- FS
12	1		*FRT LH GRILLE	Cracked	125.55 FS	*125.55 FS
13	1		*FRT RH GRILLE	Cracked	167.45 FS	*167.45 FS
14	1		*GROMMET	* Check	0.80 FS	*- FS
15	1		*PLAQUE 74MM	Necessary	76.55 FS	*76.55 FS
16	1		*FRONT PANEL V STRUT	* Check	135.90 FS	*- FS
17	1		*AIR DUCT	* Check	562.10 FS	*- FS
18	1		*RH HEADLIGHT LED TECHNOLOGY	* Check	2,503.55 FS	*- FS
19	1		*ULTRASONIC SENSOR BLACK	* Check	269.65 FS	*- FS
20	1		*DECOUPING RING PDC TORQUE CONVERTER	* Check	5.65 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 5,647.20 1,357.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SUPPLY FRONT EMBOSS NUMBER PLATE	New	83.00	83.00
2	TO REPLACE FRONT BUMPER, CARRIER, INNER SUPPORT AND ATTACHEMENTS	New	1,275.00	850.00
3	TO RESPRAY FRONT BUMPER AND AFFECTED AREAS	New	1,038.00	1,038.00
4	TO REPLACE RIGHT HEADLAMP * Check	New	481.00	0.00
5	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	177.00
6	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE FRONT SECTION FOR PROPER FUNCTION	New	177.00	177.00
Gross Labour Cost (\$\$)			3,231.00	2,325.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >