



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: EMILY TAN			Ref: CS/FCI24090353/Avp3e2(N) Date: 30/06/2025 Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SH 9703D	Veh. Inspected	SFH 3609L
	Policy No.	D-24101861MFCT	Coverage (\$)	0.00
	Claim No.	D24008196MFCT	Excess (\$)	0.00
	Assign From	BETTY WONG	Assign Date	18/09/2024
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MERCEDES BENZ C200	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WDD2050422R225138	Colour	GREY
	Odometer	127566 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	245/35 R19	MICHELIN	6 mm
	L/H Front Tyre	245/35 R19	MICHELIN	6 mm
	R/H Rear Tyre	245/35 R19	MICHELIN	6 mm
	L/H Rear Tyre	245/35 R19	MICHELIN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	16/09/2024	Inspection Date	19/09/2024
	Survey held at	CAS GARAGE PTE LTD NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT		
<b>5a. Remarks</b>				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	