

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Richard Ang Wei Guang

Date: 20 Sep 2024

Preliminary Advice

Vehicle No	: SNL2534J	Accident Date	: 18/09/2024
Make	: KIA CERATO	Policy No.	: 1003048537
Assignment Date	: 19/09/2024	Excess	: S\$500.00
Date of Inspection	: 19/09/2024	Est. Duration of Repair	: 4
Inspection At	: AUTOBACS CAR CARE (SINGAPORE) PTE LTD (HQ) 8 KAKI BUKIT AVE.4, #08-45/46 PREMIER@KAKI BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,504.80
Revised Amount	:S\$	5,233.65
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,233.65

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	64,000.00
COE / PARF Rebate	:S\$	26,655.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,345.00

Remarks

- (x) The vehicle is economical for repair
- () The vehicle is not economical for repair
- (x) Part-by-Part repair
- () Lump Sum repair

- (x) Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.
At the time of inspection, all the tyres of the insured vehicle were found to be in good serviceable condition with remaining tread depth of approximately 5 mm and braking system are in order.
Pending part prices from repairer. The vehicle repair on part by parts basis due to no 2nd hand parts available.