



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: MARCUS XIAO

Ref: CS/INC24090355/Anh3e2(N)

Date: 22/07/2025

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GBG 1844P	<b>Veh. Inspected</b>	PD 5852P
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1295662-002	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	JESS TOH	<b>Assign Date</b>	19/09/2024

#### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA HIACE SUPER GL	<b>c.c</b>	2754
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2022
<b>Chassis No.</b>	GDH2111007107	<b>Colour</b>	YELLOW
<b>Odometer</b>	232407 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195 R15C	MICHELIN	6 mm
<b>L/H Front Tyre</b>	195 R15C	MICHELIN	6 mm
<b>R/H Rear Tyre</b>	195 R15C	MICHELIN	6 mm
<b>L/H Rear Tyre</b>	195 R15C	MICHELIN	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

#### 5. General Information

<b>Accident Date</b>	16/09/2024	<b>Inspect Date / Time</b>	19/09/2024 ( 03:26 PM )
<b>Survey held at</b>	TSL AUTO PRO SELECTION PTE LTD BLK 1 KAKI BUKIT AVENUE 6 #01-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

#### 5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>16 Working Days</b>
--	------------------------