

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	MO FIRST OARITA		•			
MS	MS FIRST CAPITAL		Ref:	CS/FCI24060172/Knh3e2		
	16 RAFFLES QUAY #42-01 HONG LEONG BUILDING		Date:	20/06/2024		
	SINGAPORE 048581		Code:	FCI2		
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHA 7209U	Veh. Inspected	SLE 9833K		
	Policy No.	D-24101861MFCT	Coverage	0		
	Claim No.	D24005177MFCT	Excess	\$0.00		
	Assign From	CAROLINE CABRERA	Assign Date	20/06/2024		
2.	. Vehicle Details					
	Make & Model	HONDA VEZEL (A)	C.C	1496		
	Engine No.	L15B4028542	Year of Reg.	10/06/2016		
	Chassis No.	RU11108539	Colour	METALLIC PEARL WHITE		
	Odometer	- KM	Steering	IN ORDER		
	Brakes	IN ORDER	General	GOOD		
	Modification(s)	RIMS: SPORTS RIM	•			
3.	3. Conditions of Tyres					
		Size	Make	Balance (mm)		
	R/H Front Tyre	215/60R16	MICHELIN	8		
	L/H Front Tyre	215/60R16	MICHELIN	8		
	R/H Rear Tyre	215/60R16	MICHELIN	8		
	L/H Rear Tyre	215/60R16	MICHELIN	8		
4.	4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. THE UNDERCARRIAGE AND BODY						
STRUCTURE AFFECTED DUE TO COLLISION.						
DAMAGES SEE DETAILS.						
5.	5. General Information					
		40/00/0004		00/00/0004		

5.	General Information				
	Accident Date	10/06/2024	Inspection Date 23/08/2024		
	Survey held at	S & H MOTOR PTE LTD - 160 SIN MIN 575722	NG DRIVE #07-02 SIN MING AUTOCITY SINGAPORE		

5a. Remarks

- A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
- B) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
- C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 23 Working Days