

ASS. REC. BY:

REF:

F621

CS/FC124060172/Knh3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

23 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV. / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SL E 9833/Kr Regn: 001 16

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel C.C. 1496

Colour

M. P. White A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RUI 1108539

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F: 215/60R16
R:BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

d mm

Rear

R/Bal.

d mm

L/Bal.

p mm

L/Bal.

p mm

D.O.A.

10/6/24

D.O.I.

23/8/2024

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / UIC / Rooftop or

& FR

The UIC / Chassis frame / Body Structure affected due to collision. ✓

Date / Time

Action / Instruction

1/ 21 Rm @ 15,000 Max (Red. \$ 18954.93, 54%)

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

23

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$



☎ 6453 4730
☎ 6457 1931
✉ enquiry@sh-motor.com

WORKSHOP

160 Sin Ming Drive
#07-02 Sin Ming AutoCity
Singapore 575722

S&H Motor Pte Ltd

Co. Reg. No. : 198701322K
GST Reg. No.: M2-0076269-0

SH/2024/0121/TP

19/8/2024

Not authorized
C11 Reg @ 15,800.00 max
Presumably After Paim
23 days

Kenneth
96910663

23/8/24

M/s First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

File No :

Date :

Estimated cost of repair for vehicle no: SLE9833K Honda Vezel
Accident involving vehicle no: SLE9833K & SHA7209U On 10/6/2024

Description	Quantity	List Price
Front bumper	1	\$ 852.10 ✓
Front bumper lower lid	1	\$ 381.00 ✓
Front bumper lower grille	1	\$ 189.00 ✓
Front bumper reinforcement	1	\$ 385.00 ✓
Front bumper tow cover	1	\$ 19.00 ✓
Front bumper side retainer @\$38.00	2	\$ 76.00 ✓
Front bumper fog lamp @\$327.70	2	\$ 655.40 ✓
Front bumper fog lamp garnish @\$112.50	2	\$ 225.00 ✓
Front bumper car plate moulding	1	\$ 124.20 X
Main windscreen	1	\$ 1,335.00 ✓
Main windscreen moulding	1	\$ 180.00 ✓
Radar sensor	1	\$ 1,380.00 X
Front fender @\$596.80	2	\$ 1,193.60 ✓
Front fender arch garnish @\$189.50	2	\$ 379.00 ✓
Headlamp @\$1782.50	2	\$ 3,565.00 ✓
Headlamp lower bracket @\$89.50	2	\$ 89.50 ✓
Front radiator grille	1	\$ 421.00 ✓
Front radiator grille chrome moulding	1	\$ 385.00 ✓
Front radiator grille "Honda Logo" emblem	1	\$ 48.90 ✓
Horn	1	\$ 102.30 X
Bonnet	1	\$ 922.00 ✓
Bonnet hinge @\$48.90	2	\$ 97.80 ✓
Bonnet lock	1	\$ 122.00 ✓
Bonnet lock bracket	1	\$ 65.00 ✓
Bonnet insulator	1	\$ 122.90 ✓
Front support top panel	1	\$ 711.00 ✓
Front support panel top garnish	1	\$ 185.50 ✓
Dash board assy	1	\$ 655.50 X
Air con condenser	1	\$ 750.20 ✓
Radiator	1	\$ 1,298.00 X
Radiator bracket @\$25.00	2	\$ 50.00 ✓
Radiator side garnish @\$78.50	2	\$ 157.00 ✓
Radiator fan motor assy	1	\$ 620.00 X
Rear bumper	1	\$ 786.20 ✓
Rear bumper side retainer @\$49.00	2	\$ 98.00 ✓



6453 4730

6457 1931

enquiry@sh-motor.com

WORKSHOP

160 Sin Ming Drive
#07-02 Sin Ming AutoCity
Singapore 575722

S&H Motor Pte Ltd

Co. Reg. No. : 198701322K

GST Reg. No.: M2-0076269-0

Rear bumper reflector @\$121.00
Rear bumper side @\$215.50
Rear bumper under cover
Rear fender @\$858.00
Rear fender inner trim @\$365.80
Rear fender arc garnish @\$172.00
Tail gate
Tail gate reflector @\$335.00
Tail gate lock
Tail gate lock catch
Tail gate inner trim board
Tail gate inner board pocket handle
Tail gate wiper motor
Tail gate weatherstrip
Tail gate "Vezel" emblem
Tail gate "Honda Logo" emblem
Tail gate outer garnish
Tail gate shock absorber @\$199.00
Tail lamp @\$485.00
Tail lamp panel @\$165.00
Rear end panel
Rear end panel top garnish
Rear floor panel
Rear floor panel under cover
Rear floor panel top cover
Rear shock absorber @\$385.00
Rear axle beam
Rear wheel bearing @\$263.50
Rear exhaust silencer
Rear exhaust silencer mounting @\$35.00

2	\$	Sn	242.00	X
2	\$	Bu	431.00	✓
1	\$	Sn	241.50	X
2	\$	Bu 1 Bz	1,716.00	✓
2	\$	Refurn	731.60	✓
2	\$	Bu	344.00	✓
1	\$	Bz	998.30	✓
2	\$	Sn	670.00	X
1	\$	Od	321.00	✓
1	\$	Oii	45.80	✓
1	\$	Bu	198.50	✓
1	\$	Sn	45.00	X
1	\$	Sn	268.00	X
1	\$	Paupii	298.00	50 Sn
1	\$	na	58.00	✓
1	\$	na	45.00	✓
1	\$	Sn Cat	265.70	work
2	\$	Sn	398.00	X
2	\$	Com	970.00	✓
2	\$	Bz	330.00	✓
1	\$	Bz	623.00	✓
1	\$	na	198.00	✓
1	\$	Bz	1,025.40	✓
1	\$	Bu	241.50	✓
1	\$	Od	269.90	✓
2	\$	Sn	770.00	X
1	\$	Sn	1,650.00	X
2	\$	na	527.00	X
1	\$	Bz	598.74	✓
2	\$	Tn	70.00	✓
			\$	33,218.04
LESS 20%			\$	6,643.61
			\$	26,574.43

Special Nett

Front number plate & holder
Front bumper clips
Front fender inner shield clip
Front audio player
Bonnet insulator clips
Rear tyre rh
Reverse sensor
Rear number plate & holder
Rear bumper clips

1	\$	Od	70.00	45 Sn
set	\$	na	50.00	✓
set	\$	na	40.00	✓
1	\$	Sn	550.00	X
set	\$	na	30.00	✓
1	\$	Sn	320.00	X
set	\$	na	250.00	200 Sn
1	\$	Com	70.00	45 Sn
set	\$	na	50.00	✓



☎ 6453 4730
 📠 6457 1931
 ✉ enquiry@sh-motor.com

WORKSHOP

160 Sin Ming Drive
 #07-02 Sin Ming AutoCity
 Singapore 575722

S&H Motor Pte Ltd

Co. Reg. No. : 198701322K
 GST Reg. No.: M2-0076269-0

Rear end panel top garnish clips	set	\$	15.00	✓
Rear end panel sealant	1	\$	40.00	30sn
Rear floor panel sealant	1	\$	60.00	30sn
Rear reverse camera	1	\$	400.00	X
Rear fender inner trim clips	set	\$	80.00	✓
Tail gate chrome trimming	1	\$	150.00	X
Tail gate windscreen sealant	1	\$	60.00	80sn
Tailgate inner trim board clips	set	\$	60.00	✓
Tail gate remote buzzer	1	\$	95.50	X

Labour

To dismantle, replace, cut, weld, knock out dents to straighten accident damaged parts.	\$	1,800.00	✓
Remove & refix dashboard and internal wiring	\$	300.00	X
Remove & replace front radar sensor & conduct distance safety setting	\$	200.00	801
Remove & refix aircon condenser and refill aircon gas	\$	120.00	1001
Remove & refix radiator, top up coolant & conduct pressure test	\$	90.00	501
Remove & refix tailgate windscreen glass	\$	120.00	✓
Remove & refix/replace rear bumper reverse sensor & conduct distance safety setting	\$	70.00	501
Remove & refix/replace rear reverse camera & conduct distance safety setting	\$	70.00	401
Remove & refix/replace rear exhaust system	\$	90.00	601
Transfer of existing tailgate mechanism to new tailgate	\$	90.00	601
Remove & refix/replace rear undercarriage work	\$	350.00	2001
To conduct wheel alignment	\$	100.00	601
To conduct rear chassis alignment	\$	250.00	✓
Conduct water leak test for rear portion associated repair work	\$	40.00	201
Wiring /bulb checking/focusing	\$	100.00	401
To putty & spray paint accident damaged parts and adjacent panels	\$	2,000.00	✓
	\$	34,754.93	

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: