

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No.

19-9607198-R

		Affiliated to Federation Inte	ernationale Des Experts En A	Automobile
MS	MS FIRST CAPITAL	L INSURANCE LTD	Ref:	CS3/FCI24090359/Enp3
	16 RAFFLES QUAY	(Date:	30/09/2024
	#42-01 HONG LEO			FCI2
	SINGAPORE 04858		Code:	
1.		<u> </u>	ulars :- PRE-REPAIR SURVE	
	Insured Veh.	SHC 8582Z	Veh. Inspected	SFL 101H
	Policy No.	D-24101861MFCT	Coverage	0
	Claim No.	D24008146MFCT	Excess	\$0.00
	Assign From	JOANNE	Assign Date	19/09/2024
2.			Vehicle Details	
	Make & Model	TOYOTA LEXUS ES300H	C.C	2494
	Engine No.	2AR1199044	Year of Reg.	29/01/2015
	Chassis No.	JTHBW1GG302085693	Colour	WHITE
	Odometer	53055 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	FAIR
	Modification(s)	RIMS: SPORTS RIM	<u> </u>	
3.	Conditions of Tyres			
		Size	Make	Balance (mm)
	R/H Front Tyre	215/55R17	BRIDGESTONE	5
	L/H Front Tyre	215/55R17	BRIDGESTONE	5
	R/H Rear Tyre	215/55R17	BRIDGESTONE	5
	L/H Rear Tyre	215/55R17	BRIDGESTONE	5
4.	Description of Damages			
THE	VEHICLE SUSTAIN	ED DAMAGES AT THE FRONT N	I/S PORTION.	
5.	General Information			
	Accident Date	14/09/2024	Inspection Date	24/09/2024 (09:56)
	Survey held at	GL AUTO		
		BLK 6 DEFU LANE 10		
		#01-550 SINGADORE 530187		
5a.		#01-550 SINGAPORE 539187	Remarks	

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

D)MARKET VALUE:\$30,000.00 (EST)

E)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days

CTY

CHEN TSUE YEE