

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EG124090360/EQP3M4**Date:** 26/06/2025REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** PC5707G**Insured Vehicle No :** YP3459K

Date of Loss: 05/09/2024

Nature of Claim: TP

Claim No: CDMCG24002287

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **PC5707G**

Make &amp; Model: YUTONG ZK6122HE9, 8.8 D (A)

Engine No: ISL89E532022212155

Reg. Date: 07/04/2017 (Man. Year: 2016)

Chassis No: LZYTATE62G1029419

Colour: Multi-colour

Odometer: 393237 km

Engine Capacity: 8880 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70R22.5

Rear Tyre Size: 275/70R22.5

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	15,565.00	6,759.00	8,806.00	56.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,800.00	2,625.00	4,175.00	61.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>22,365.00</b>	<b>9,384.00</b>	<b>12,981.00</b>	<b>58.04</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,500.00</b>		
<b>(S\$)</b>	22,365.00	7,500.00	14,865.00	66.47
<b>+ GST 9.00/9.00% (S\$)</b>	2,012.85	675.00	1,337.85	66.47
<b>Nett Amount (S\$)</b>	<b>24,377.85</b>	<b>8,175.00</b>	<b>16,202.85</b>	<b>66.47</b>

INSPECTION

Date of Assignment: 19/09/2024

Date Inspected: 04/06/2025

Inspected At:

THINK ONE AUTOCARE PTE LTD  
60 JALAN LAM HUAT,  
#02-32, CARROS CENTRE  
SINGAPORE 737869

Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Jun 2025)	
Parts:	N/A	YUTONG ZK6122HE9 8.8 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC5707G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR CORNER LOWER PANEL RH	Dented	8,200.00 F	*6,560.00 FL
2	1		*REAR CORNER INNER BRACKET RH	Not Necessary	580.00 F	*- FL
3	1		*RIGHT REAR TAIL LAMP	Broken	950.00 F	*950.00 FL
4	1		*RIGHT REAR FOG LAMP (WITH REFLECTOR)	Not Necessary	780.00 F	*- FL
5	1		*RIGHT END COMPARTMENT DOOR RH	Repair	2,985.00 F	*- FL
6	2		*RIGHT END COMPARTMENT DOOR LOCK RH	Not Necessary	370.00 F	*- FL
7	2		*RIGHT END COMPARTMENT DOOR HINGE RH	Not Necessary	210.00 F	*- FL
8	2		*AIR BRACING	Not Necessary	410.00 F	*- FL
9	2		*LATCH	Not Necessary	190.00 F	*- FL
10	1		*SIDE MARKER LAMP	Not Necessary	60.00 F	*- FL
11	1		*REVERSE SENSOR (4PCS/SET)	Not Necessary	400.00 FS	*- FS
12	2		*SIDE PANEL SEAL GLASS SEALANT	Not Necessary	280.00 FS	*- FS
13	1		*SIDE PANEL INNER SEALANT	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,565.00	7,510.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	751.00
Total Parts (\$\$)	15,565.00	6,759.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE DAMAGED BODY PARTS WITH ALL NECESSARY COMPONENTS/ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY REPAIR, RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS/ATTACHMENTS	New	3,800.00	1,750.00
2	TO SPRAY PAINT REPLACED/REPAIRED BODY PARTS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	2,500.00	875.00
3	TO REMOVE,REFIX REAR RIGHT SIDE PANEL GLASS AND WATER TEST	New	500.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,800.00</b>	<b>2,625.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >