



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 6328E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	EMBLEM-BACK DOOR NV350 (N)	NECESSARY	122.40	122.40
1	EMBLEM-REAR NISSAN (N)	NOT NECESSARY	72.20	-
10	CLIP RR BUMPER @ SGD\$1.50 EACH (N)	NECESSARY	15.00	15.00
1	RR BUMPER (N)	DENTED	743.00	743.00
1	RH RR COMB LAMP (N)	BROKEN	275.30	275.30
	LESS 20% DISCOUNT		-245.58	-231.14
			982.32	924.56
	<u>SPECIAL NETT ITEMS</u>			
1	SENSOR-REVERSE (SN)	NOT NECESSARY	250.00	-
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
1	70KM/H STICKER (SN)	NECESSARY	15.00	15.00
1	LABEL-PAX 10 (SN)	NECESSARY	15.00	15.00
			330.00	30.00
	<u>LABOUR</u>			
	LABOR CHARGES TO REPAIR RH RR FENDER, RH RR TAIL LAMP PANEL LOWER & TAIL GATE RENEW RR BUMPER.		2,150.00	645.00
	CHARGES TO SPRAY PAINTING SAME.		1,400.00	1,050.00
	PERFORM RUST PROOFING LH RR FENDER AND TAIL LAMP PANEL LOWER.	NOT NECESSARY	240.00	-
	REMOVE AND INSTALL REVERSE SENSOR.		55.00	55.00
	RENEW RH RR COMB LAMP.		80.00	80.00
			3,925.00	1,830.00
	GRAND TOTAL		5,237.32	2,784.56
RECOMMENDED COST OF REPAIRS				2,784.56

Report Ref No. CS/CTI24090361/Uvh3m4(N)

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.