

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24090366/TPA3Q2**Date:** 24/07/2025REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7230003043
Claimant Vehicle No : FBM7572C **Insured Vehicle No :** SNJ3655Y
 Date of Loss: 16/09/2024 Nature of Claim: TP Claim No: 6737457262SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBM7572C**
 Make & Model: HONDA CB400X, 399cc Engine No: NC47E5200019
 Reg. Date: 21/03/2018 (Man. Year: 2017) Chassis No: JH2NC4790HK200022
 Colour: White Odometer: 0 km
 Engine Capacity: 399 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70 R17 Rear Tyre Size: 160/60 R17
 Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,400.00	4,860.00	540.00	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	500.00	300.00	200.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,900.00	5,160.00	740.00	12.54
Approved Total (Overridden) (S\$)		4,100.00		
Nett Amount (S\$)	5,900.00	4,100.00	1,800.00	30.51
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 20/09/2024
 Date Inspected: 20/09/2024 Inspected At: Pang Scooter Service (HQ)
 BLK 1006 BUKIT MERAH LANE 2 #01-06
 Singapore 159762
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE END	Cut	85.00 F	*85.00 FL
2	1		*HANDLE BAR	Bent	185.00 F	*185.00 FL
3	1		*RH MIRROR	Cut	85.00 F	*85.00 FL
4	1		*BRAKE LEVER	Broken	95.00 F	*95.00 FL
5	1		*CRASH BAR	Dented	450.00 F	*450.00 FL
6	1		*F WHEEL RIM	Bent	620.00 F	*620.00 FL
7	1		*F BRAKE DISC	Bent	320.00 F	*320.00 FL
8	1		*MUFFLER ASSEMBLY	Dented	680.00 F	*680.00 FL
9	1		*MUFFLER GUARD	Cut	120.00 F	*120.00 FL
10	1		*UNDER BRACKET	Bent	385.00 F	*385.00 FL
11	1		*SET STEERING CONE	Necessary	165.00 F	*165.00 FL
12	2		*FORK INNER TUBE	Bent	560.00 F	*560.00 FL
13	2		*FORK OIL SEAL	Necessary	150.00 F	*150.00 FL
14	1		*RADIATOR ASSEMBLY	Bent	480.00 F	*480.00 FL
15	1		*COOLANT	Necessary	45.00 F	*45.00 FL
16	1		*WINDSHIELD	Cut	285.00 F	*285.00 FL
17	1		*GEAR PEDAL	Bent	185.00 F	*185.00 FL
18	1		*REAR BOX	Cut	285.00 F	*285.00 FL
19	2		*FORK OIL	Necessary	100.00 F	*100.00 FL
20	2		*F WHEEL BEARING	Necessary	80.00 F	*80.00 FL
21	1		*MUFFLER JOINT GASKET	Necessary	40.00 F	*40.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	5,400.00	5,400.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	540.00
Total Parts (S\$)	5,400.00	4,860.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	500.00	300.00
Gross Labour Cost (\$\$)			500.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >