

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/AIG24090367/AUA3Q2  
**Date:** 14/01/2025**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 7240023684   |
| <b>Claimant Vehicle No :</b> | SJX7507P                             | <b>Insured Vehicle No :</b> | SMZ7870T     |
| Date of Loss:                | 19/09/2024                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 0038308783SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |             |
|-----------------------------|-----------------------------------|-------------|-------------|
| Reg No:                     | <b>SJX7507P</b>                   | Engine No:  | L15A2331982 |
| Make & Model:               | HONDA FREED, 1.5 G (A)            | Chassis No: | GB31031603  |
| Reg. Date:                  | 08/07/2010 (Man. Year: 2008)      | Odometer:   | 144921 km   |
| Colour:                     | Blue                              |             |             |
| Engine Capacity:            | 1496 cc                           |             |             |
| Market Value/New Car Price: | N/A                               |             |             |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |             |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 195/55 R15    | Rear Tyre Size:  | 195/55 R15    |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts   | 7,440.72          | 6,685.84          | 754.88            | 10.15         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour  | 2,640.00          | 1,710.00          | 930.00            | 35.23         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing  | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>10,080.72</b>  | <b>8,395.84</b>   | <b>1,684.88</b>   | <b>16.71</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>6,700.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 10,080.72         | 6,700.00          | 3,380.72          | 33.54         |
| <b>+ GST 9.00/9.00% (S\$)</b>                   | 907.26            | 603.00            | 304.26            | 33.54         |
| <b>Nett Amount (S\$)</b>                        | <b>10,987.98</b>  | <b>7,303.00</b>   | <b>3,684.98</b>   | <b>33.54</b>  |
| <b>+ Loss of Use (6.0 x S\$60.00/day) (S\$)</b> |                   | 360.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 2.18              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>7,665.18</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>              |                   | <b>7,650.00</b>   |                   |               |

**INSPECTION**

|                             |            |               |   |
|-----------------------------|------------|---------------|---|
| Date of Assignment:         | 20/09/2024 |               | Modern Automotive Pte Ltd (HQ)                            |
| Date Inspected:             | 20/09/2024 | Inspected At: | Blk 3023A Ubi Road 1, #01-61 & #01-58<br>Singapore 408717 |
| Estimated Period of Repair: | 6.0 days   |               |   |

**Adjuster:** ADRIAN LING**Manager:** NA MENG YAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                        | Condition     | Repairer's  | Amount       |
|-----|-----|----------|------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                      | Deformed      | 988.20 FL   | *988.20 FL   |
| 2   | 2   |          | *FRONT BUMPER SIDE HOLDER -LH & RH | Not Necessary | 60.20 FL    | *- FL        |
| 3   | 1   |          | *FRONT BUMPER REINFORCEMENT        | Dented        | 351.60 FL   | *351.60 FL   |
| 4   | 1   |          | *FRONT GRILLE                      | Cracked       | 312.90 FL   | *312.90 FL   |
| 5   | 1   |          | *FRONT GRILLE TOP MOULDING         | Cracked       | 100.20 FL   | *100.20 FL   |
| 6   | 2   |          | *FRONT GRILLE CENTRE MOULDING      | Not Necessary | 110.40 FL   | *- FL        |
| 7   | 1   |          | *FRONT GRILLE LOWER MOULDING       | Not Necessary | 108.20 FL   | *- FL        |
| 8   | 1   |          | *FRONT GRILLE LOGO                 | Missing       | 40.90 FL    | *40.90 FL    |
| 9   | 2   |          | *HEADLAMP                          | Cracked       | 1,737.40 FL | *1,737.40 FL |
| 10  | 2   |          | *HEADLAMP TOP PANEL                | Buckled       | 190.80 FL   | *190.80 FL   |
| 11  | 1   |          | *BONNET                            | Dented        | 986.40 FL   | *986.40 FL   |
| 12  | 1   |          | *BONNET LOCK                       | Jammed        | 95.10 FL    | *95.10 FL    |
| 13  | 2   |          | *BONNET HINGE                      | Bent          | 148.20 FL   | *148.20 FL   |
| 14  | 1   |          | *FRONT SUPPORT PANEL               | Buckled       | 663.40 FL   | *663.40 FL   |
| 15  | 1   |          | *AIR CON CONDENSER                 | Dented        | 936.60 FL   | *936.60 FL   |
| 16  | 2   |          | *AIR CON CONDENSER MOUNTING        | Necessary     | 50.00 FL    | *50.00 FL    |
| 17  | 1   |          | *AIR CON FAN BLADE                 | Not Necessary | 46.50 FL    | *- FL        |
| 18  | 1   |          | *AIR CON FAN COWLING               | Cracked       | 100.90 FL   | *100.90 FL   |
| 19  | 1   |          | *AIR CON FAN MOTOR                 | Not Necessary | 233.60 FL   | *- FL        |
| 20  | 1   |          | *RADIATOR                          | Dented        | 1,355.80 FL | *1,355.80 FL |
| 21  | 2   |          | *RADIATOR TOP BRACKET              | Not Necessary | 21.00 FL    | *- FL        |
| 22  | 1   |          | *RADIATOR FAN COWLING              | Cracked       | 98.90 FL    | *98.90 FL    |
| 23  | 1   |          | *RADIATOR FAN MOTOR                | Not Necessary | 308.90 FL   | *- FL        |
| 24  | 1   |          | *RADIATOR FAN BLADE                | Not Necessary | 54.80 FL    | *- FL        |
| 25  | 1   |          | *FRONT NUMBER PLATE                | Cracked       | 30.00 FS    | *30.00 FS    |
| 26  | 1   |          | *FRONT NUMBER PLATE HOLDER         | Deformed      | 30.00 FS    | *30.00 FS    |
| 27  | 1   |          | *SET FRONT BUMPER CLIPS            | Necessary     | 30.00 FS    | *30.00 FS    |
| 28  | 1   |          | *SET FRONT GRILLE CLIPS            | Necessary     | 20.00 FS    | *20.00 FS    |
| 29  | 1   |          | *COOLANT                           | Necessary     | 50.00 FS    | *50.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |                 |                 |
|--|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>9,260.90</b> | <b>8,317.30</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | 1,820.18        | 1,631.46        |
| <b>Total Parts (\$\$)</b>                                  | <b>7,440.72</b> | <b>6,685.84</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars  | Lab.Type | Repairer's      | Amount          |
|--------------------------------|--|----------|-----------------|-----------------|
| <b>Labour Items</b>            |  |          |                 |                 |
| 1                              | TO KNOCKING & PULL OUT FRONT PORTION & RENEW ABOVE PARTS | New      | 1,200.00        | 800.00          |
| 2                              | TO PUTTY & SPRAY UP PAINT WORKS                          | New      | 1,000.00        | 700.00          |
| 3                              | TO CHECK WIRING  | New      | 50.00           | 30.00           |
| 4                              | TO REMOVE CONDENSER & TOP-UP GAS                         | New      | 120.00          | 60.00           |
| 5                              | TO REMOVE RADIATOR & TOP-UP COOLANT                      | New      | 120.00          | 60.00           |
| 6                              | TO APPLY TUFF COAT                                       | New      | 150.00          | 60.00           |
| <b>Gross Labour Cost (S\$)</b> |  |          | <b>2,640.00</b> | <b>1,710.00</b> |

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**