

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG24060173/AQP3M4**Date:** 01/08/2024REFERENCE

Insured/Claimant: GANDAVALLI RAMANIAH PRASANNA

Policy No: 7220098855-01

Date of Loss: 08/06/2024

Nature of Claim: OD

Claim No: 6309773611SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKG6447M**

Make &amp; Model: AUDI A4, 2.0 TFSI S-TRONIC (A)

Engine No: DEM033319

Reg. Date: 29/08/2022 (Man. Year: 2021)

Chassis No: WAUZZZF49MA077992

Colour: Black

Odometer: 20624 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$180,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17

Rear Tyre Size: 225/50 R17

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	19,658.00	4,207.60	15,450.40	78.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,322.00	1,822.00	2,500.00	57.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>23,980.00</b>	<b>6,029.60</b>	<b>17,950.40</b>	<b>74.86</b>
<b>- Excess (S\$)</b>	550.00	550.00	0.00	0.00
<b>(S\$)</b>	23,430.00	5,479.60	17,950.40	76.61
<b>+ GST 9.00/9.00% (S\$)</b>	2,108.70	493.16	1,615.54	76.61
<b>Nett Amount (S\$)</b>	<b>25,538.70</b>	<b>5,972.76</b>	<b>19,565.94</b>	<b>76.61</b>

INSPECTION

Date of Assignment: 25/06/2024

Date Inspected: 24/06/2024 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,670.00 FS	*2,136.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	420.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	90.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	245.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - CENTER	Not Necessary	329.00 FS	*- FS
6	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	176.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	Cracked	329.00 FS	*262.80 FS
8	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	338.00 FS	*- FS
9	2		*FRONT BUMPER AIR GUIDE GRILLE TRIM - LH / RH	Not Necessary	120.00 FS	*- FS
10	1		*RADIATOR GRILLE	Cracked	1,949.00 FS	*1,559.20 FS
11	2		*FRONT PARKING AID SENSOR	Not Necessary	572.00 FS	*- FS
12	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	11.00 FS	*- FS
13	1		*FRONT LOCK CARRIER TOP BRACKET	Not Necessary	173.00 FS	*- FS
14	1		*FRONT FOAM FILLER PIECE	Torn	237.00 FS	*189.60 FS
15	1		*FRONT REINFORCEMENT BEAM	Not Necessary	1,033.00 FS	*- FS
16	2		*FRONT REINFORCEMENT BEAM BRACKET - LH / RH	Not Necessary	570.00 FS	*- FS
17	1		*LOCK CARRIER TOP BRACKET SUPPORT - LH / RH	Not Necessary	74.00 FS	*- FS
18	1		*OUTSIDE TEMP SENSOR BRACKET	Not Necessary	30.00 FS	*- FS
19	1		*LED HEADLIGHT - LH	Not Necessary	9,204.00 FS	*- FS
20	3		*LED HEADLIGHT SPACER	Not Necessary	150.00 FS	*- FS
21	1		*LIFT CYLINDER - LH	Not Necessary	252.00 FS	*- FS
22	1		*LIFT CYLINDER BRACKET	Not Necessary	8.00 FS	*- FS
23	1		*LIFT CYLINDER HOSE	Not Necessary	118.00 FS	*- FS
24	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
25	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS
					<b>Total Parts (S\$)</b>	<b>19,658.00      4,207.60</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,400.00	500.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	1,800.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,322.00</b>	<b>1,822.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >