



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKK 4410K

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BONNET	NOT NECESSARY	\$860.60	\$0.00
1	FRONT HEADLAMP	NOT NECESSARY	\$1,075.60	\$0.00
1	FRONT HEADLAMP LOWER BRACKET	NOT NECESSARY	\$95.00	\$0.00
1	RADIATOR GRILLE BASE	CUT/CRACKED	\$302.40	\$302.40
2	RADIATOR GRILLE CHROME TOP	SERVICEABLE	\$77.20	\$0.00
1	RADIATOR GRILLE CHROME LOWER CHROME	SCRATCHED	\$275.40	\$115.20
1	RADIATOR GRILLE LOGO	NOT NECESSARY	\$414.80	\$0.00
1	FRONT BUMPER	CUT/TORN	\$779.20	\$779.20
1	FRONT BUMPER FOG LAMP	NOT NECESSARY	\$740.90	\$0.00
1	FRONT BUMPER FOG LAMP GRILLE	NOT NECESSARY	\$42.50	\$0.00
1	FRONT BUMPER LOWER GRILLE	CUT/TORN	\$646.50	\$646.50
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	\$230.20	\$0.00
2	FRONT BUMPER SIDE RETAINERS	NOT NECESSARY	\$77.00	\$0.00
1	FRONT BUMPER PDC SENSOR	SERVICEABLE	\$280.00	\$0.00
1	FRONT FENDER	NOT NECESSARY	\$529.50	\$0.00
1	FRONT SUPPORT PANEL	NOT NECESSARY	\$748.50	\$0.00
	LESS 20.00% DISCOUNT		(\$1,435.06)	(\$368.66)
			\$5,740.24	\$1,474.64

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	\$80.00	\$30.00
1	FRONT NUMBER PLATE WITH HOLDER (SN)	SERVICEABLE	\$50.00	\$0.00
			\$130.00	\$30.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	NOT NECESSARY	\$80.00	\$20.00
	TO REMOVE AND REFIT FRONT SENSOR		\$150.00	\$30.00
	TO APPLY UNDERCOATING		\$200.00	\$0.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT		\$1,800.00	\$250.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS		\$1,600.00	\$300.00
			\$3,830.00	\$600.00
GRAND TOTAL			\$9,700.24	\$2,104.64
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$1,500.00
Report Ref No: CS/INC24090370/Uvh3				

TOTAL FOR SPARE PARTS: \$ 5,870.24 \$ 1,504.64
TOTAL FOR LABOUR : \$ 3,830.00 \$ 600.00
TOTAL REPAIR COST: \$ 9,700.24 \$ 2,104.64

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.