

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS INCOME INSURAN		CE LTD	Ref:	CS/INC24090370/Uvh3	
	75 BRAS BASAH R		Date:	01/10/2024	
	INCOME CENTRE	SINGAPORE 189557	Code:	INC	
1.		Policy Particulars :- THIRD PARTY CLAIM			
•	Insured Veh.	SLS 1944C	Veh. Inspected	SKK 4410K	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1295942-002	Excess	\$0.00	
	Assign From	EILEEN LEE	Assign Date	20/09/2024	
2.	Assignition	Vehicle Details			
	Make & Model	HONDA ODYSSEY E:HEV ABSOLUTE	c.c	1993	
	Engine No.	LFA2142212	Year of Reg.	22/12/2022	
	Chassis No.	RC41302211	Colour	BLACK	
	Odometer	34560 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.		Conditions of Tyres			
		Size	Make	Balance (mm)	
	R/H Front Tyre	235/50R18	BRIDGESTONE	8	
	L/H Front Tyre	235/50R18	BRIDGESTONE	8	
	R/H Rear Tyre	235/50R18	BRIDGESTONE	8	
	L/H Rear Tyre	235/50R18	BRIDGESTONE	8	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.					
DAMAGES SEE DETAILS.					
5.		General Information			
	Accident Date	29/08/2024	Inspection Date	23/09/2024 (10:30)	
	Survey held at	rvey held at WE GARAGE – 11 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY @ KAKI BUKIT, SINGAF 417883			
5a.		Remarks			
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					

Estimate Days of Repair