

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS MS FIRS	S MS FIRST CAPITAL INSURANCE LTD		Ref:	CS/FCI24090371/Kvp3m4	
16 RAFF	16 RAFFLES QUAY			05/11/2024	
#42-01 HONG LEONG BUILDING SINGAPORE 048581		Date: Code:	FCI2		
	ORE 04636				
1. Policy Particulars :- THIRD PARTY CLAIM  Insured Veh. SHD 4494R Veh. Inspected SMH 6379Y					
		SHD 4494R	Veh. Inspected	SMH 6379Y	
Policy N		- -	Coverage	0	
Claim N		D24008223MFCT	Excess	\$0.00	
Assign	From	CAROLINE	Assign Date	19/09/2024	
2.			le Details		
Make &		TOYOTA NOAH (A)	C.C	1797	
Engine		2ZR2B97874	Year of Reg.	29/01/2019	
Chassis		ZWR800353546	Colour	METALLIC PEARL WHITE	
Odomet		122971 KM	Steering	IN ORDER	
Brakes		IN ORDER	General	GOOD	
Modifica	ation(s)	RIMS: STANDARD ALLOY RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
R/H Fro	nt Tyre	195/65R15	MICHELIN	8	
L/H Fro	nt Tyre	195/65R15	MICHELIN	8	
R/H Rea	ar Tyre	195/65R15	MICHELIN	8	
L/H Rea	r Tyre	195/65R15	MICHELIN	8	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
DAMAGES SEE DETAILS.					
5. General Information					
Accider	nt Date	18/09/2024	Inspection Date	16/10/2024	
Survey		CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761	·		
5a. Remarks					
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
B)THE INSPE	ECTION WAS	S CONDUCTED ON A"WITHOUT PF		EPAIRS.	

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days