10/7/24, 3:16 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III24090374/KNP3M4

07/10/2024 Date:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0008927_02

Claimant Vehicle SLM2853G Insured Vehicle No: SLR5567L

No:

Date of Loss: 18/09/2024 Nature of Claim: ΤP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM2853G**

Make & Model: HONDA HR-V, 1.5 DX CVT (A) Engine No: L15B4531886

Reg. Date: 27/03/2017 (Man. Year: 2016) Chassis No: JHMRU1810GX201886

Colour: Metallic Grey Odometer: 83487 km

Engine Capacity: 1496 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Pre-accident Condition: Engine Modification: No Handbrake (Serviceable): Yes

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16 Front Left Side: Rear Left Side: Michelin 9 mm Michelin 9 mm Front Right Side: Michelin 9 mm Rear Right Side: Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,272.32	2,811.00	7,461.32	72.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	1,580.00	1,800.00	53.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S	\$) 13,652.32	4,391.00	9,261.32	67.84
Approved Total (Overridden) (S	\$)	3,500.00		
(S	\$) 13,652.32	3,500.00	10,152.32	74.36
+ GST 9.00/9.00% (S	\$) 1,228.71	315.00	913.71	74.36
Nett Amount (S	\$) 14,881.03	3,815.00	11,066.03	74.36

INSPECTION

Date of Assignment: 19/09/2024

> **EM SOLUTION PTE LTD** 160 SIN MING DRIVE

Date Inspected: 23/09/2024 Inspected At: #03-18/19 SIN MING AUTOCITY

SINGAPORE 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG Manager: **HUEY YON**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 07 Oct 2024)

Parts: HONDA HR-V 1.5 DX CVT (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLM2853G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE	Bent	1,287.10 FL	*1,100.70 FL
2	1	*SET TAILGATE GLASS MOULDING	Necessary	121.60 FL	*121.60 FL
3	1	*TAILGATE OUTER GARNISH	Serviceable	391.40 FL	*- FL
4	1	*TAILGATE EMBLEM LOGO	Not Necessary	48.80 FL	*- FL
5	1	*TAILGATE EMBLEM HRV	Necessary	68.80 FL	*68.80 FL
6	1	*TAILGATE EMBLEM I-VTEC	Necessary	68.80 FL	*68.80 FL
7	2	*TAILGATE LAMPS - L/R	Serviceable	820.40 FL	*- FL
8	1	*TAILGATE INNER LOCK	Dented	281.30 FL	*131.80 FL
9	1	*TAILGATE INNER TRIM BOARD	Serviceable	481.60 FL	*- FL
10	1	*TAILGATE INNER PULL POCKET	Serviceable	86.90 FL	*- FL
11	2	*TAILGATE DAMPERS - L/R	Serviceable	372.20 FL	*- FL
12	2	*TAILGATE STOPPERS	Serviceable	25.20 FL	*- FL
13	2	*TAILLAMPS - L/R	Serviceable	976.20 FL	*- FL
14	1	*REAR BUMPER	Bent	791.60 FL	*791.60 FL
15	2	*REAR BUMPER REFLECTORS - L/R	Serviceable	179.80 FL	*- FL
16	2	*REAR BUMPER SIDES - L/R	Serviceable	482.40 FL	*- FL
17	2	*REAR BUMPER SIDE RETAINERS - L/R	Serviceable	97.20 FL	*- FL
18	1	*REAR END PANEL	Buckled	659.10 FL	*517.00 FL
19	1	*REAR END PANEL GARNISH	MTG Cracked	211.60 FL	*160.50 FL
20	1	*REAR EXHAUST SILENCER	Repair	576.50 FL	*- FL
21	1	*REAR EXHAUST INSULATOR	Serviceable	120.30 FL	*- FL
22	2	*REAR EXHAUST MOUNTINGS	Serviceable	56.40 FL	*- FL
23	1	*REAR FLOOR BOARD	Serviceable	370.60 FL	*- FL
24	1	*REAR FLOOR SPONGE TRAY	Serviceable	321.60 FL	*- FL
25	1	*REAR FLOOR PANEL	Repair	871.90 FL	*- FL
26	1	*REAR FLOOR PANEL UNDERCOVER	Serviceable	286.90 FL	*- FL
27	2	*REAR FENDER PROTECTORS - L/R	Serviceable	683.20 FL	*- FL
 28	1	*REAR SMART KEYLESS ANTENNA	Cracked	191.20 FL	*85.20 FL
29	1	*REAR SMART KEYLESS BUZZLE	Serviceable	199.60 FL	*- FL
30	1	*TAILGATE W/STRIP	Dented/Distorted	210.20 FN	*84.20 F
	•	(\$168.40) (50%) (SN)	2 0.110 4, 2 10101 104		- · · · · · · · · · · · · · · · · · · ·
31	1	*SET TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
32	1	*SET TAILGATE OUTER GARNISH CLIP	Not Necessary	80.00 FS	*- FS
33	1	*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
34	1	*SET REAR NO. PLATE	Serviceable	60.00 FS	*- FS
35	1	*REAR REVERSE CAMERA	Serviceable	450.00 FS	*- FS
36	1	*SET REAR REVERSE SENSOR - 4 PCS	Dented/Shorted	480.00 FS	*200.00 FS
F=Fra	anchise part. S=Spc	Nett. L=ListItemDisc. N=NettItemDisc.		P	

Sub Total (S\$)	12,540.40	3,420.20
- List Item Discount on L Items 20.00/20.00% (S\$)	2,226.04	609.20
- Nett Item Discount on N Items 20.00/0.00% (S\$)	42.04	0.00
,		

2,811.00 Total Parts (S\$) 10,272.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE, REFIX TAILGATE GLASS	New	180.00	120.00
3	TRANSFER & REINSTALL TAILGATE COMPONENTS TO NEW TAILGATE	New	150.00	60.00
4	TO REMOVE, REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	60.00
5	TO REMOVE, REFIX REAR REVERSE SENSOR / CAMERA	New	80.00	60.00
6	TO REMOVE, REFIX REAR EXHAUST	New	80.00	0.00
7	TO RESPRAY PAINTING AND ETC	New	1,200.00	600.00
8	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS	New	1,400.00	600.00
9	TO RESPRAY UNDERCOATING	New	120.00	60.00
	Gross Labour	Cost (S\$)	3,380.00	1,580.00
	Report was unsubmitted during this p	orint-out.		

< END OF ESTIMATES >