

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24090375/AVP3E2**Date:** 20/01/2025REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SKQ399E **Insured Vehicle No :** SLX784C

Date of Loss: 18/09/2024 Nature of Claim: TP Claim No: DMPC2401233H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKQ399E**

Make & Model: SEAT ALHAMBRA, 2.0 STYLE 220 (A) Engine No: DED035769

Reg. Date: 20/10/2020 (Man. Year: 2019) Chassis No: VSSZZZ7NZLV501111

Colour: Grey Odometer: 141935 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,311.36	18,569.00	9,742.36	34.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,280.00	2,310.00	1,970.00	46.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,591.36	20,879.00	11,712.36	35.94
Approved Total (Overridden) (S\$)		16,700.00		
Nett Amount (S\$)	32,591.36	16,700.00	15,891.36	48.76

INSPECTION

Date of Assignment: 20/09/2024

Date Inspected: 20/09/2024 Inspected At: JEC AUTO SERVICE PTE LTD (HQ)
1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE (EST) : \$110,000.00

LTA REBATE : \$ 55,387.00

NETT VALUE : \$ 54,613.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan 2025)
Parts:	M1-MPV	SEAT ALHAMBRA 2.0 STYLE 220 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ399E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR NUMBER PLATE LAMP	Not Necessary	190.00 FL	*- FL
2	1		*REAR BUMPER	Distorted	4,850.00 FL	*4,850.00 FL
3	2		*REAR BUMPER SIDE HOLDER	Not Necessary	370.00 FL	*- FL
4	1		*REAR BUMPER REFLECTOR	N/S Cracked	370.00 FL	*185.00 FL
5	1		*REAR BUMPER LOWER GARNISH	Deformed	1,250.00 FL	*1,250.00 FL
6	1		*REAR BUMPER REINFORCEMENT	Dented	1,850.00 FL	*1,650.00 FL
7	1		*REAR BUMPER TOW COVER	Deformed	160.00 FL	*160.00 FL
8	1		*REAR BUMPER SIDE UNDERCOVER	N/S Torn	270.00 FL	*135.00 FL
9	1		*REAR BUMPER CENTRE GUIDE	Cracked	285.00 FL	*285.00 FL
10	1		*REAR BUMPER SPONGE	Cracked	385.00 FL	*385.00 FL
11	1		*REAR BUMPER SENSOR (4PCS)	Damaged (3Pcs Only)	1,440.00 FL	*1,080.00 FL
12	4		*REAR BUMPER SENSOR HOLDER	Necessary	100.00 FL	*100.00 FL
13	1		*REAR BUMPER SENSOR WIRE HARNESS	Snapped	550.00 FL	*550.00 FL
14	1		*REAR BUMPER LOWER BRACKET	N/S Bent	570.00 FL	*285.00 FL
15	1		*REAR END PANEL	Dented	1,210.00 FL	*1,210.00 FL
16	1		*REAR END PANEL TOP GARNISH	Cracked	425.00 FL	*425.00 FL
17	1		*TAILLAMP	N/S Cut	2,520.00 FL	*1,260.00 FL
18	1		*TAILGATE	Distorted	4,255.00 FL	*4,255.00 FL
19	1		*TAILGATE LOCK	Jammed	825.00 FL	*745.00 FL
20	1		*TAILGATE WEATHERSTRIPE	Not Necessary	850.00 FL	*- FL
21	2		*TAILGATE REFLECTOR	Not Necessary	2,100.00 FL	*- FL
22	1		*TAILGATE INNER TRIM BOARD	Cracked	980.00 FL	*980.00 FL
23	1		*TAILGATE GLASS MOULDING	Necessary	290.00 FL	*290.00 FL
24	1		*SEAT LOGO	Necessary	105.00 FL	*105.00 FL
25	1		*ALHAMBRA WORDING	Necessary	125.00 FL	*125.00 FL
26	1		*FLOOR PANEL	Repair	2,905.00 FL	*- FL
27	1		*FLOOR PANEL TOP BOARD	Not Necessary	595.00 FL	*- FL
28	1		*REAR EXHAUST PIPE	Repair	598.60 FL	*- FL
29	1		*REAR EXHAUST MOUNTING	Not Necessary	28.50 FL	*- FL
30	1		*REAR EXHAUST GASKET	Not Necessary	48.30 FL	*- FL
31	1		*REAR EXHAUST PIPE HEAT SHIELD	Not Necessary	290.00 FL	*- FL
32	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
33	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
34	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
35	2		*SET REAR BUMPER SIDE UNDERCOVER CLIPS	Necessary	20.00 FS	*10.00 FS
36	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
37	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
38	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
39	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
40	1		*FLOOR PANEL INSULATION PAD	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Sub Total (\$)						31,390.40
						20,600.00
- List Item Discount on L Items 10.00/10.00% (\$)						3,079.04
						2,031.00
Total Parts (\$)						28,311.36
						18,569.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVE AND REFIT PARTS	New	1,600.00	1,000.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	800.00
3	WIRING CHECK	New	100.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE REAR CAMERA	New	100.00	50.00
6	TO REMOVE UPHOLSTERY AND REAR SEAT	New	350.00	80.00
7	TO SPRAY TUFF COAT	New	150.00	60.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	60.00
9	TO REMOVE TAILGATE GLASS	New	180.00	120.00
10	TO REMOVE EXHAUST PIPE	New	150.00	60.00
Gross Labour Cost (\$\$)			4,280.00	2,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >