

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI24060174/ANH3M4**Date:** 16/01/2025REFERENCE

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMCG23009203
Claimant Vehicle No :	GBE7924M	Insured Vehicle No :	YP3659A
Date of Loss:	18/06/2024	Nature of Claim:	TP
		Claim No:	CDMCG24001493

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE7924M		
Make & Model:	TOYOTA DYNA 150 MANUAL, 3.0 D (M)	Engine No:	1KD2589252
Reg. Date:	28/03/2016 (Man. Year: 2016)	Chassis No:	JTFAT35Y90K206103
Colour:	Black	Odometer:	363714 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	165R13C
Front Left Side:	Wanli 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Wanli 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,377.00	2,219.25	4,157.75	65.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	940.00	1,560.00	62.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,877.00	3,159.25	5,717.75	64.41
Approved Total (Overridden) (S\$)		2,500.00		
Nett Amount (S\$)	8,877.00	2,500.00	6,377.00	71.84

INSPECTION

Date of Assignment:	20/06/2024	
Date Inspected:	24/06/2024	Inspected At:
Estimated Period of Repair:	3.0 days	

D&K AUTOMOTIVE SERVICES PTE LTD (HQ)
BLK C KAKI BUKIT AVENUE 6
#01-59 KAKI BUKIT AUTOBAY
SINGAPORE 417883

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Jan 2025)	
Parts:	N/A	TOYOTA DYNA 150 MANUAL 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE7924M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT CORNER PANEL RH	Not Necessary	680.00 FL	*- FL
2	1		*FRONT SIDE MIRROR GARNISH	Cracked	430.00 FL	*430.00 FL
3	1		*FRONT SIDE MIRROR RH	Missing	285.00 FL	*285.00 FL
4	1		*FRONT SIDE MIRROR ARM RH	Not Necessary	585.00 FL	*- FL
5	1		*FRONT DOOR RH	Dented	2,250.00 FL	*1,794.00 FL
6	1		*FRONT DOOR INNER TRIM RH	Not Necessary	750.00 FL	*- FL
7	1		*FRONT DOOR INNER TRIM BOARD SPEAKER RH	Not Necessary	325.00 FL	*- FL
8	1		*FRONT DOOR OUTER GLASS MOULDING RH	Not Necessary	289.00 FL	*- FL
9	1		*FRONT DOOR OUTER GLASS WEATHERSTRIP RH	Not Necessary	450.00 FL	*- FL
10	1		*FRONT DOOR OUTER HANDLE RH	Not Necessary	225.00 FL	*- FL
11	1		*FRONT DOOR GLASS RH	Cut	890.00 FL	*410.00 FL
12	1		*FRONT DOOR STEP GARNISH RH	Not Necessary	350.00 FL	*- FL
13	1		*FRONT DOOR STEP PANEL RH	Not Necessary	525.00 FL	*- FL
14	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	202.00 FL	*- FL
15	10		*FRONT DOOR STEP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
16	10		*FRONT DOOR INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
17	1		*REGISTER COMPANY STICKER	Necessary	100.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,436.00	2,949.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,059.00	729.75
Total Parts (\$\$)	6,377.00	2,219.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	KNOCKING ADJUST SIDE ON AFFECTED AREAS	New	1,000.00	400.00
2	TO PUTTY, RE-SPRAY PAINTING AND POLISH SIDE AFFECTED AREAS	New	1,000.00	400.00
3	TO RUST PROOF AFFECTED SIDE AREAS	New	100.00	30.00
4	TO CHECK WIRING AND RECTIFY FRONT	New	100.00	30.00
5	TO REMOVE AND TRANSFER FRONT DOOR ASSY IN ORDER TO WORKS	New	200.00	40.00
6	TO REMOVE AND REFIT FRONT DOOR GLASS ASSY	New	100.00	40.00
Gross Labour Cost (\$\$)			2,500.00	940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >