10/9/24, 8:06 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited Our File No: CS/ICS24090380/NQP3M4

10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Date: 09/10/2024

REFERENCE

Insured/Claimant: MUHAMMAD ADIB BIN AZIS Policy No: MPC23P00248600

Date of Loss: 18/09/2024 Nature of Claim: OD Claim No: DMPC2401242H/ST/INVESTIGATION

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SML1665H

Make & Model: BMW 316I, 1.6 AT D/AB 4DR ABS HID (A) Engine No: A967J394N13B16A Reg. Date: 21/03/2013 (Man. Year: 2012) Chassis No: WBA3A12050J719782

Colour: Grey Odometer: 0 km

Engine Capacity: 1598 cc
Market Value/New Car

Price: S\$72,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/80 R19 Rear Tyre Size: 275/80 R19
Front Left Side: Falken 0 mm Rear Left Side: Falken 5 mm
Front Right Side: Falken 0 mm Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total	1 (S\$) 0.00	0.00	0.00	
- Excess	(S\$) 0.00	500.00	-500.00	
Nett Amount	t (S\$) 0.00	-500.00	500.00	

INSPECTION

Date of Assignment: 20/09/2024 Present Location: VERVE MOTORWORKZ PTE LTD

VERVE MOTORWORKZ PTE LTD

Date Inspected: 23/09/2024 Inspected At: 25 KAKI BUKIT ROAD 4,

#03-39 SYNERGY@KB,

SINGAPORE 417800

Estimated Period of Repair: 0.0 days

Adjuster: SHIAU CHAN Manager: Muhammad Nazril Bin Abdullah

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value: \$72,000.00

OMV: \$34,105.00

PARF Rebate (1): \$ 0.00

Quota Premium Paid: \$46,482.00

COE Rebate (2): \$33,024.00

Total Rebate (1) + (2) = : \$33,024.00

The total amount incurred will be Market Value \$72,000.00 minus Total Rebate \$33,024.00 = \$38,976.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Oct 2024)

Parts: 143 BMW 316I 1.6 AT D/AB 4DR ABS HID (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SML1665H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >