



Your Ref : DMPC2401242H/ST

Date: 08th October 2024

Our Ref : CS/ICS24090380/Nqp3m4

M/s ECICS LTD

10 Eunost Road 8

Singapore Post Centre #09-04A

Singapore 408600

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SML 1665H
ACCIDENT ON 18/09/2024**

Instruction was received to inspect the vehicle Reg. No. SML 1665H. The inspection was conducted on 23/09/2024 at the premises of M/s Verve Motorworkz Pte Ltd 25 Kaki Bukit Road 4, #03-39 Synergy@Kb, Singapore 417800.

The following vehicle information was recorded:

Registration Number	: SML 1665H
Make/Model	: BMW 316I 1.6 AT D/AB 4DR ABS HID
Year of Registration	: 2013
Body Colour	: Grey
Chassis Number	: WBA3A12050J719782
Engine Capacity	: 1598 cc
Speedometer Reading	: N/A (Battery Melted)

The vehicle caught fire. The cause of fire probably due to electrical short circuit. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$	72,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$	33,024.00)
Nett Liability	S\$	38,976.00
	=====	

Vehicle Inspected By:



MUHD NAZRIL (NAZ)
Technical Investigator
LL.B. (Hons) London



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.