



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLS 9698K

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	CUT/TORN	\$1,989.61	\$1,874.44
1	FRONT BUMPER PDC SENSOR - RH	SERVICEABLE	\$283.55	\$0.00
1	FRONT BUMPER SIDE GRILLE - RH	NOT NECESSARY	\$102.63	\$0.00
1	FRONT BUMPER TOP SEAL	NOT NECESSARY	\$110.20	\$0.00
1	FRONT BUMPER SIDE BRACKET - RH	NOT NECESSARY	\$89.95	\$0.00
1	FRONT FENDER - RH	TO REPAIR SEE LABOUR	\$1,042.16	\$0.00
1	FRONT FENDER INNER SHIELD	NOT NECESSARY	\$141.52	\$0.00
1	FRONT HEADLAMP - RH	SCRATCHED/CRACKED	\$3,968.21	\$3,968.21
1	FRONT KNUCKLE ARM - RH	NOT NECESSARY	\$1,210.43	\$0.00
1	FRONT WHEEL HUB BEARING	NOT NECESSARY	\$599.61	\$0.00
1	FRONT LOWER CONTROL ARM	NOT NECESSARY	\$561.20	\$0.00
	<b>LESS 10.00% DISCOUNT</b>		(\$1,009.91)	(\$584.27)
			\$9,089.16	\$5,258.38

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT SPORT WHEEL - RH (SN)	CUT/WARPED	\$1,490.31	\$800.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	\$60.00	\$40.00
			\$1,550.31	\$840.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK FRONT ELECTRICAL WIRING		\$50.00	\$20.00
	TO REMOVE, REFIX FRONT UNDERCARRIAGE	NOT NECESSARY	\$250.00	\$0.00
	TO CHECK WHEEL ALIGNMENT		\$120.00	\$60.00
	TO RESPRAY PAINTING & ETC		\$800.00	\$300.00
	PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER - RH		\$800.00	\$400.00
			\$2,020.00	\$780.00

<b>GRAND TOTAL</b>			<b>\$12,659.47</b>	<b>\$6,878.38</b>
--------------------	--	--	--------------------	-------------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>		<b>\$5,500.00</b>
<b>Report Ref No: CS/INC24090381/Uvh3</b>		

**TOTAL FOR SPARE PARTS: \$10,639.47 \$ 6,098.38**  
**TOTAL FOR LABOUR : \$ 2,020.00 \$ 780.00**  
**TOTAL REPAIR COST: \$12,659.47 \$ 6,878.38**

## CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.