



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24090394/Uvp3
16 RAFFLES QUAY	Date:	10/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 3007L	Veh. Inspected	SLZ 9779Z
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24008252MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	23/09/2024

2. Vehicle Details

Make & Model	TOYOTA VIOS E (A)	C.C	1496
Engine No.	2NR5207974	Year of Reg.	26/03/2018
Chassis No.	MR2B23F3401116097	Colour	RED
Odometer	134042 KM	Steering	DAMAGED
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/60 R15	MICHELIN	6
L/H Front Tyre	185/60 R15	MICHELIN	6
R/H Rear Tyre	185/60 R15	MICHELIN	6
L/H Rear Tyre	185/60 R15	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/09/2024	Inspection Date	24/09/2024
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days