

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24090396/UMA3Q2
Date: 06/12/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MPC0004715_02
Claimant Vehicle No : SLC6845G Insured Vehicle No : SLN6255B
Date of Loss: 23/09/2024 Nature of Claim: TP Claim No: MPC2024D0011258

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLC6845G
Make & Model: HONDA VEZEL, 1.5 X (A) Engine No: L15B4031410
Reg. Date: 23/05/2016 (Man. Year: 2015) Chassis No: RU11111409
Colour: White Odometer: 199011 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,469.90	4,631.20	12,838.70	73.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,180.00	1,640.00	2,540.00	60.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,649.90	6,271.20	15,378.70	71.03
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	21,649.90	5,000.00	16,649.90	76.91
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		5,402.18		
Global Sum Settlement (S\$)		5,400.00		

INSPECTION

Date of Assignment: 24/09/2024
Date Inspected: 24/09/2024 Inspected At: Choo Motor Spray Painter (HQ)
1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit
Singapore 417883
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Nov 2024)
Parts:	M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC6845G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	110.20 F	*110.20 FL
2	1		*TAILGATE	Dented / Bent	1,099.20 F	*1,099.20 FL
3	1		*TAILGATE VEZEL EMBLEM	Necessary	66.80 F	*66.80 FL
4	1		*TAILGATE H LOGO	Not Necessary	45.00 F	*- FL
5	1		*TAILGATE OUTER HANDLE GARNISH	Not Necessary	450.00 F	*- FL
6	1		*TAILGATE REFLECTORS	N/S Cracked / O/SNot Necessary	772.40 F	*386.20 FL
7	1		*TAILGATE INNER LOCK	Not Necessary	199.80 F	*- FL
8	1		*TAILGATE LOCK STRIKER	Not Necessary	66.00 F	*- FL
9	1		*TAILGATE INNER TRIM BOARD	Deformed / Cracked	435.00 F	*300.80 FL
10	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
11	1		*TAILGATE WEATHERSTRIP	Twisted	288.00 F	*288.00 FL
12	1		*REAR BUMPER	Dented	980.00 F	*761.00 FL
13	1		*REAR BUMPER SIDES	N/S Buckled / O/SNot Necessary	470.20 F	*235.10 FL
14	1		*REAR BUMPER REFLECTORS	N/S Cracked / O/SNot Necessary	302.00 F	*151.00 FL
15	1		*REAR BUMPER UNDER COVER	Deformed / Twisted	541.00 F	*322.80 FL
16	1		*SET REAR BUMPER UNDER COVER CLIPS	Not Necessary	50.00 F	*- FL
17	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
18	1		*REAR END PANEL	Dented / Bent	665.20 F	*517.00 FL
19	1		*REAR END PANEL TOP GARNISH	Twisted	341.10 F	*204.80 FL
20	1		*TAILLAMPS	N/S Cracked	1,300.00 F	*480.60 FL
21	2		*TAILLAMP HOUSING PANELS	Repair	700.00 F	*- FL
22	1		*REAR BUZZLE SENSOR	Cracked	98.00 F	*98.00 FL
23	2		*REAR FENDERS	Repair	2,180.00 F	*- FL
24	1		*REAR FENDER OUTER PROTECTORS	N/S Torn / O/S Not Necessary	760.00 F	*292.50 FL
25	2		*REAR FENDER INNER TRIM BOARDS	Not Necessary	790.00 F	*- FL
26	1		*REAR FLOOR PANEL	Not Necessary	1,280.00 F	*- FL
27	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	522.00 F	*- FL
28	1		*REAR FLOOR PANEL TOP TRAY	Not Necessary	585.00 F	*- FL
29	1		*REAR EXHAUST	Not Necessary	765.00 F	*- FL
30	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	108.00 F	*- FL
31	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
32	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*20.00 FS
33	1		*REAR BUMPER TOP CHROME PLATE	Not fitted	200.00 FS	*- FS
34	1		*REAR END PANEL TOP GARNISH CROME PLATE	Not fitted	200.00 FS	*- FS
35	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*40.00 FS
36	1		*SET REAR BUMPER REVERSE SENSOR	Malfunction	280.00 FS	*200.00 FS
37	1		*SET REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
38	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)17,469.905,714.00

- List Item Discount on L Items 0.00/20.00% (\$\$)0.001,082.80

Total Parts (\$\$)17,469.904,631.20

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	30.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO TRANSFER TAILGATE MECHANIS	New	100.00	60.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	60.00
6	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	New	180.00	0.00
7	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
8	TO SPRAY RUST PROOFING	New	100.00	50.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,800.00	600.00
10	TO PUTTY & SPRAY PAINTING	New	1,500.00	700.00
Gross Labour Cost (\$\$)			4,180.00	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >