



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SGN 8211Z

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	TORN	\$795.00	\$795.00
1	FRONT BUMPER FOG LAMP LH	NOT NECESSARY	\$275.00	\$0.00
1	FRONT BUMPER FOG LAMP RING LH	NOT NECESSARY	\$125.80	\$0.00
1	FRONT BUMPER FOG LAMP COVER LH	NOT NECESSARY	\$126.00	\$0.00
2	FRONT BUMPER SIDE RETAINER @\$55.00	NOT NECESSARY	\$110.00	\$0.00
1	FRONT BUMPER BOTTOM GARNISH	NOT NECESSARY	\$174.20	\$0.00
1	FRONT BUMPER LOWER SIDE GARNISH LH	NOT NECESSARY	\$69.10	\$0.00
1	FRONT BUMPER SPONGE	NOT NECESSARY	\$176.80	\$0.00
1	HEADLAMP (HID) LH	CUT	\$2,983.72	\$2,650.00
1	FRONT FENDER LH	DENTED	\$804.00	\$689.00
1	FRONT FENDER COWLING LH	NOT NECESSARY	\$178.00	\$0.00
1	FRONT WHEEL HOUSE PANEL LH	NOT NECESSARY	\$615.80	\$0.00
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	\$155.00	\$0.00
	LESS 25.00% DISCOUNT		(\$1,647.11)	(\$1,033.50)
			\$4,941.31	\$3,100.50

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	\$50.00	\$30.00
1	SET FRONT BUMPER BOTTOM GARNISH CLIP (SN)	NOT NECESSARY	\$40.00	\$0.00
1	SET FRONT SPORT RIMS (SN)	NOT NECESSARY	\$1,200.00	\$0.00
1	FRONT TYRE LH (SN)	NOT NECESSARY	\$380.00	\$0.00
1	SET FRONT FENDER COWLING CLIP (SN)	NOT NECESSARY	\$50.00	\$0.00
			\$1,720.00	\$30.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK		\$1,000.00	\$450.00
	TO SPRAY PAINT		\$1,000.00	\$400.00
	TUFF COAT	NOT NECESSARY	\$250.00	\$0.00
	WIRING, BULB CHECKING		\$150.00	\$30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REFOCUS HEADLAMP BEAM	NOT NECESSARY	\$100.00	\$0.00
	FOUR WHEEL ALIGNMENT (BEFORE & AFTER)	NOT NECESSARY	\$120.00	\$0.00
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	NOT NECESSARY	\$180.00	\$0.00
			\$2,800.00	\$880.00
GRAND TOTAL			\$9,461.31	\$4,010.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$3,200.00
Report Ref No: CS/FCI24090404/Anp3m4				

MARKET VALUE: \$62,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$28,409.00=NETT VALUE: \$33,591.00

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.