

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	MS FIRST CAPITAL	INSURANCE LTD	Ref:	CS/FCI24090404/Anp3m4	
	16 RAFFLES QUAY	IC PLUI DING	Date:	21/11/2024	
	#42-01 HONG LEON SINGAPORE 04858		Code:	FCI2	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 7181Y	Veh. Inspected	SGN 8211Z	
	Policy No.	D-24101861MFCT	Coverage	0	
	Claim No.	D24008307MFCT	Excess	\$0.00	
	Assign From	HARMINDER	Assign Date	23/09/2024	
2.	Vehicle Details				
	Make & Model	TOYOTA WISH	c.c	1798	
	Engine No.	2ZR0A44031	Year of Reg.	08/01/2018	
	Chassis No.	JTDGG20W40J008574	Colour	GREY	
	Odometer	133495 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	3. Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	195/65R15	WEST LAKE	6	
	L/H Front Tyre	195/65R15	WEST LAKE	6	
	R/H Rear Tyre	195/65R15	WEST LAKE	6	
	L/H Rear Tyre	195/65R15	WEST LAKE	6	
4.	Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.					
DAMAGES SEE DETAILS.					
5.	5. General Information				
	Accident Date	20/09/2024	Inspection Date	24/09/2024	
	Survey held at	KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978			
5a.	5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT.  B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  C)NACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT ALITHOPISED REPAIRS					
A)DAMAGES CONSISTENT TO ACCIDENT REPORT.					

**Estimate Days of Repair**