



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNN 4408S

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR RIM	NOT NECESSARY	\$1,549.20	\$0.00
1	REAR WHEEL BEARING & HUB ASSY RH	NOT NECESSARY	\$761.20	\$0.00
1	REAR WHEEL AXLE	NOT NECESSARY	\$2,547.00	\$0.00
1	REAR ABSORBER RH	NOT NECESSARY	\$787.00	\$0.00
1	REAR FENDER RH	TO REPAIR SEE LABOUR	\$3,110.90	\$0.00
1	REAR FENDER QUARTER GLASS MOULDING WITH GLASS RH	NOT NECESSARY	\$1,233.40	\$0.00
1	REAR FENDER INNER SHIELD RH	NOT NECESSARY	\$251.90	\$0.00
1	REAR FENDER AIR DUCT RH	NOT NECESSARY	\$114.20	\$0.00
1	REAR BUMPER	CRUSHED	\$1,880.20	\$1,445.00
1	REAR BUMPER REFLECTOR RH	BROKEN	\$289.00	\$131.00
2	REAR BUMPER SIDE RETAINER LH / RH @\$85.90	BROKEN	\$171.80	\$85.90
1	TAIL LAMP LOWER GARNISH RH	BROKEN	\$349.20	\$244.00
	<b>LESS 25.00% DISCOUNT</b>		(\$3,261.25)	(\$476.48)
			<b>\$9,783.75</b>	<b>\$1,429.42</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	TYRE (SN)	NOT NECESSARY	\$300.00	\$0.00
1	RIM (SN)	NOT NECESSARY	\$1,200.00	\$0.00
1	SIDE SKIRT CLIPS (SN)	NOT NECESSARY	\$50.00	\$0.00
1	ROCKER PANEL SEALANT (SN)	NOT NECESSARY	\$80.00	\$0.00
1	REAR FENDER SEALANT (SN)	NOT NECESSARY	\$80.00	\$0.00
1	REAR FENDER QUARTER GLASS SEALANT (SN)	NOT NECESSARY	\$80.00	\$0.00
1	REAR FENDER QUARTER GLASS DAMPING SEAL (SN)	NOT NECESSARY	\$30.00	\$0.00
1	BUMPER CLIP (SN)	NECESSARY	\$50.00	\$30.00
			<b>\$1,870.00</b>	<b>\$30.00</b>

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	NOT NECESSARY	\$300.00	\$0.00
	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS. INCLUSIVE OF THE REPAIR OF REAR FENDER RH		\$2,400.00	\$300.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS		\$2,400.00	\$500.00
	TO APPLY ANTI-RUST COATINGS ON ALL AFFECTED AREAS	NOT NECESSARY	\$300.00	\$0.00
	TO RNR REAR UNDERCARRIAGE TO FACILITATE REPAIRS	NOT NECESSARY	\$250.00	\$0.00
	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	NOT NECESSARY	\$120.00	\$0.00
	TO RNR REAR SLIDING DOOR TO FACILITATE REPAIRS	NOT NECESSARY	\$250.00	\$0.00
	TO RNR REAR SLIDING DOOR MECHANISM TO FACILITATE REPAIR	NOT NECESSARY	\$150.00	\$0.00
	TO RE-ALIGN REAR SLIDING DOOR RAILING ALIGNMENT	NOT NECESSARY	\$150.00	\$0.00
	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	NOT NECESSARY	\$300.00	\$0.00
	TO RNR REAR FENDER FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	NOT NECESSARY	\$300.00	\$0.00
	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS		\$200.00	\$50.00
	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS		\$300.00	\$50.00
	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD		\$120.00	\$50.00
			\$7,540.00	\$950.00
<b>GRAND TOTAL</b>			<b>\$19,193.75</b>	<b>\$2,409.42</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>\$1,950.00</b>
Report Ref No: CS/FCI24060177/Evh3e2				

**CTY**

STEVE CHEN TSUE YEE