

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLP 7791C

	REPLACEMENT OF PARTS					
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	REAR BUMPER	DENTED/DEFORMED	\$484.60	\$484.60		
1	R/R TAILLAMP	NOT NECESSARY	\$350.00	\$0.00		
1	REAR BOOT	TO REPAIR SEE LABOUR	\$1,500.00	\$0.00		
1	REAR END PANEL	TO REPAIR SEE LABOUR	\$245.00	\$0.00		
1	REAR BUMPER LOWER DIFFUSER	DISTORTED	\$173.20	\$173.20		
1	REAR BUMPER LH REFLECTOR	NOT NECESSARY	\$68.00	\$0.00		
1	REAR BUMPER REINFORCEMENT	BENT	\$314.20	\$314.20		
	LESS 0.00 / 20.00% DISCOUNT		\$0.00	(\$194.40)		
		\$3,135.00	\$777.60			

Labour					
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
TO REMOVE REAR BUMPER, AND BUMPER REINFORCEMENT OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR BOOT AND REAR END PANEL		\$800.00	\$500.00		
TO RESPRAY PAINTING		\$800.00	\$600.00		
		\$1,600.00	\$1,100.00		
GRAND TOTAL		\$4,735.00	\$1,877.60		
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$1,500.00		
Report Ref No: CS/INC24090409/Unh3					

TOTAL FOR SPARE PARTS: \$ 3,135.00 \$ 777.60

TOTAL FOR LABOUR: \$ 1,600.00 \$ 1,100.00

TOTAL REPAIR COST: \$ 4,735.00 \$ 1,877.60

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.