



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SJK 9256T

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	DEFORMED	\$1,265.70	\$985.00
1	FRONT BUMPER FOG LAMP COVER RH	NOT NECESSARY	\$79.20	\$0.00
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	\$184.20	\$0.00
2	FRONT BUMPER SIDE RETAINER @\$85.60	NOT NECESSARY	\$171.20	\$0.00
1	HEADLAMP RH	CRACKED	\$1,925.30	\$1,925.30
1	FRONT UPPER GRILLE	NOT NECESSARY	\$804.60	\$0.00
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	\$974.30	\$0.00
1	FRONT FENDER INNER COWLING RH	NOT NECESSARY	\$219.60	\$0.00
1	FRONT ABS SENSOR RH	NOT NECESSARY	\$397.20	\$0.00
1	FRONT STEERING RACK AND PINION	BENT	\$1,667.30	\$1,667.30
1	FRONT DRIVESHAFT RH	NOT NECESSARY	\$1,448.60	\$0.00
1	FRONT KNUCKLE ARM BEARING RH	DAMAGED	\$201.70	\$201.70
1	FRONT STABILIZER BAR LINKAGE RH	NOT NECESSARY	\$173.70	\$0.00
1	FRONT SHOCK ABSORBER RH	NOT NECESSARY	\$441.30	\$0.00
1	FRONT KNUCKLE ARM RH	DAMAGED	\$565.70	\$565.70
1	FRONT LOWER ARM RH	BENT	\$997.60	\$585.00
	LESS 25.00% DISCOUNT		(\$2,879.30)	(\$1,482.50)
			\$8,637.90	\$4,447.50

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT WHEEL RIM RH (SN)	CUT	\$914.48	\$480.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	\$80.00	\$30.00
1	SET FRONT BUMPER LOWER GRILLE CLIP (SN)	NOT NECESSARY	\$50.00	\$0.00
1	SET FRONT BUMPER UNDER COVER GARNISH CLIP (SN)	NOT NECESSARY	\$50.00	\$0.00
1	SET FRONT UPPER GRILLE CLIP (SN)	NOT NECESSARY	\$60.00	\$0.00
1	SET FRONT FENDER COWLING CLIPS (SN)	NOT NECESSARY	\$60.00	\$0.00
1	FRONT WHEEL TYRE RH (SN)	NOT NECESSARY	\$650.00	\$0.00
1	BRAKE OIL (SN)	NOT NECESSARY	\$30.00	\$0.00
			\$1,894.48	\$510.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING, REMOVING AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH		\$1,200.00	\$300.00
	SPRAY PAINTING TO AFFECTED AREA		\$1,000.00	\$400.00
	TUFF COAT		\$250.00	\$30.00
	WIRING CHECK		\$80.00	\$30.00
	REFOCUS HEADLAMP BEAM	NOT NECESSARY	\$60.00	\$0.00
	REMOVE AND REFIX STEERING RACK PINION		\$350.00	\$120.00
	REMOVE AND REFIX FRONT UNDERCARRIAGE		\$650.00	\$200.00
	FOUR WHEEL ALIGNMENT		\$120.00	\$80.00
	FRONT CHASSIS ALIGNMENT	NOT NECESSARY	\$250.00	\$0.00
	RESET ABS LIGHT	NOT NECESSARY	\$350.00	\$0.00
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	NOT NECESSARY	\$180.00	\$0.00
			\$4,490.00	\$1,160.00
GRAND TOTAL			\$15,022.38	\$6,117.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$4,900.00
Report Ref No: CS/INC24090410/Aqh3e2				

TOTAL FOR SPARE PARTS: \$ 10,532.38 \$ 4,957.50
TOTAL FOR LABOUR : \$ 4,490.00 \$ 1,160.00
TOTAL REPAIR COST: \$ 15,022.38 \$ 6,117.50

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.