1/16/25, 9:50 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI24090414/KNP3E2

Date: 16/01/2025

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MZC04317

Claimant Vehicle
SUB2222D

VN4426B

No: SLB3833R Insured Vehicle No: YN4186B

Date of Loss: 18/09/2024 Nature of Claim: TP Claim No: M2405507

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLB3833R

Make & Model: TOYOTA COROLLA, 1.3 (A) Engine No: 1ZR0G87430

Reg. Date: 18/05/2021 (Man. Year: 2021) Chassis No: MR2BE3BE600014756

Colour: Metallic Red Odometer: 59566 km

Engine Capacity: 1598 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,874.75	2,644.84	1,229.91	31.74
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,370.00	840.00	530.00	38.69
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	5,244.75	3,484.84	1,759.91	33.56
	+ GST 9.00/9.00% (S\$)	472.03	313.64	158.39	33.56
	Nett Amount (S\$)	5,716.78	3,798.48	1,918.30	33.56

INSPECTION

Date of Assignment: 24/09/2024

Date Inspected: ComfortDelGro Engineering Pte Ltd (Braddell)

27/09/2024 Inspected At: 205 Braddell Road

27/09/2024 Inspected At: 205 Braddell Road Singapore 579701

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Jan 2025)

Parts: 143 TOYOTA COROLLA 1.3 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLB3833R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT HOOD	Bent	870.00 FL	*870.00 FL
2	1		*FRT HOOD INSULATOR	Serviceable	260.00 FL	*-FL
3	1		*FRT HOOD LOCK	Repair	140.00 FL	*- FL
4	1		*FRT HOOD RUBBER	Serviceable	128.00 FL	*-FL
5	1		*FRT BUMPER LH CHROME	Serviceable	90.00 FL	*- FL
6	1		*WIPER GARNISH	Dented / Cut	770.00 FL	*727.12 FL
7	1		*LH HEADLAMP	Serviceable	900.00 FL	*- FL
8	1		*FRT WINDSCREEN	Cut	1,250.00 FL	*1,250.00 FL
9	1		*SETS FRT WINDSCREEN MOULDING	Necessary	160.00 FL	*126.00 FL
10	1		*FRT RADIATOR GRILLE (LOWER)	Dented	500.00 FL	*500.00 FL
11	1		*FRT TOW COVER	Serviceable	45.00 FL	*- FL
12	1		*SEALANT	Necessary	40.00 FS	*40.00 FS
F=Fra	anchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	5,153.00	3,513.12
			- List Item Discount on	L Items 25.00/25.00% (S\$)	1,278.25	868.28
				Total Parts (S\$)	3,874.75	2,644.84

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO KNOCK PUTTY REMOVE REFIT REALIGN AFFECTED PART	S New	600.00	300.00
2	TO PUTTY AND RESPRAY AFFECTED PARTS	New	600.00	400.00
3	HL WIRING	New	50.00	20.00
4	TO REMOVE / REFIT FRT WINDSCREEN	New	120.00	120.00
	G	ross Labour Cost (S\$)	1,370.00	840.00
	Report was unsubmitted d	uring this print-out.		

< END OF ESTIMATES >